

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna
CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION (LAGUNA WATER)

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE I (CHO-1)

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 24

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 09/08/2020-09/23/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER					
			pH/ Temperature ^A (- / °C) MDL: NA LOQ: NA	RESIDUAL CHLORINE ^B (mg/L) MDL: 0.06 LOQ: 0.20	COLIFORM ^C		HPC ^D (CFU/mL)	
			TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)				
BRGY. BANAY-BANAY								
09/21/2020 15:45	S20-6236	Water Pump, Block 63, Lakeside Nest Subdivision	7.94 / 27.4	0.11	ABSENCE	ABSENCE	< 1	
09/21/2020 15:50	S20-6237	Block 12, Lot 5, Phase 4, Lakeside Nest Subdivision	7.85 / 29.6	0.10	ABSENCE	ABSENCE	< 1	
BRGY. BANLIC								
09/10/2020 12:40	S20-5941	Water Pump, Gran Seville Subdivision	7.50 / 29.5	0.26	ABSENCE	ABSENCE	-	
09/10/2020 12:47	S20-5942	Gate Entrance, Gran Seville Subdivision	7.46 / 28.9	0.15	ABSENCE	ABSENCE	-	
BRGY. BIGAA								
09/21/2020 12:30	S20-6238	#253 Elsol Subdivision	7.51 / 29.2	0.21	ABSENCE	ABSENCE	< 1	
BRGY. GULOD								
09/08/2020 13:25	S20-5802	Water Pump, Block 12, Noah St., Celestine Ville	7.98 / 28.4	0.49	ABSENCE	ABSENCE	< 1	
09/08/2020 13:25	S20-5803	Guardhouse, Celestine Ville	7.96 / 30.1	0.14	ABSENCE	ABSENCE	< 1	
BRGY. MARINIG								
09/21/2020 12:37	S20-6226	Block 3 Lot 17, Phase 1, Celestine Homes	8.01 / 31.1	0.16	ABSENCE	ABSENCE	< 1	
09/21/2020 13:50	S20-6227	Block 23, Lot 10, Phase 1, Celestine Homes	7.90 / 30.0	0.10	ABSENCE	ABSENCE	< 1	
09/21/2020 14:15	S20-6228	Water Pump, Block 9, Carnation St., Phase 2, Celestine Homes	8.00 / 30.6	0.69	ABSENCE	ABSENCE	< 1	
09/21/2020 14:20	S20-6229	Block 9 Lot 12, Phase 2, Celestine Homes	7.96 / 29.1	0.45	ABSENCE	ABSENCE	< 1	
09/21/2020 14:45	S20-6230	Water Pump, Block 25, Phase 3, Southville	7.96 / 29.4	0.62	ABSENCE	ABSENCE	1	
09/21/2020 15:00	S20-6231	Block 19 Lot 33, Phase 3, Southville	7.85 / 28.6	0.45	ABSENCE	ABSENCE	< 1	

NOT VALID WITHOUT QR CODE



REVIEWED BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s) (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20	TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
BRGY. NIUGAN							
09/21/2020 12:40	S20-6239	Health Center, St. Francis Homes	7.45 / 29.0	0.16	ABSENCE	ABSENCE	< 1
09/21/2020 15:38	S20-6235	Block 47 Lot 101, Phase 10, Southville	7.68 / 29.8	0.12	ABSENCE	ABSENCE	< 1
09/21/2020 15:10	S20-6232	Water Pump, Block 45, Phase 8	7.93 / 29.3	0.36	ABSENCE	ABSENCE	< 1
09/21/2020 15:20	S20-6233	Health Center, Southville	7.45 / 28.6	0.25	ABSENCE	ABSENCE	< 1
09/21/2020 15:30	S20-6234	Water Pump, Block 54, Phase 10, Southville	7.89 / 28.8	0.16	ABSENCE	ABSENCE	23
09/08/2020 15:15	S20-5804	Water Pump, Southville Phase 9	7.45 / 29.8	0.38	ABSENCE	ABSENCE	< 1
09/08/2020 15:20	S20-5805	De Guzman Residence, Southville Phase 9	7.38 / 29.8	0.22	ABSENCE	ABSENCE	< 1
BRGY. SALA							
09/08/2020 15:30	S20-5806	Gate Entrance, Amaia Scapes	7.93 / 29.5	0.30	ABSENCE	ABSENCE	< 1
BRGY. SAN ISIDRO							
09/10/2020 13:40	S20-5945	Block 3 Lot 33, Multiland IV	7.45 / 29.6	0.20	ABSENCE	ABSENCE	-
09/10/2020 13:15	S20-5943	Water Pump, San Isidro Heights Subdivision	7.60 / 29.0	0.31	ABSENCE	ABSENCE	-
09/10/2020 13:25	S20-5944	Block 3 Lot 1, San Isidro Heights Subdivision	7.55 / 28.9	0.24	ABSENCE	ABSENCE	-

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: HPC – Heterotrophic Plate Count; CFU – Colony Forming Units; MDL – Method Detection Limit; LOQ – Limit of Quantification; NA – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: A – Electrometric; B – Colorimetric; C – Enzyme Substrate; D – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR CODE



REVIEWED BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna
CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE II (CHO-2)

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 20

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 09/08/2020-09/11/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
BRGY. MAMATID							
09/08/2020 11:10	S20-5798	Water Pump, Buena Rosario Subdivision	7.44 / 29.1	1.06	ABSENCE	ABSENCE	< 1
09/08/2020 16:00	S20-5799	Block 14 Lot 27, Buena Rosario Subdivision	7.77 / 30.1	0.08	ABSENCE	ABSENCE	140
09/08/2020 11:41	S20-5792	Water Pump, Block 101, Samar St., Phase 2, Mabuhay City Homes	7.32 / 27.9	0.57	ABSENCE	ABSENCE	< 1
09/08/2020 11:23	S20-5794	Water Pump, Block 141, Carmona St., Phase 2, Mabuhay City Homes	7.90 / 29.0	0.78	ABSENCE	ABSENCE	160
09/08/2020 13:30	S20-5800	Water Pump, Block 198, Galacia St., Phase 2, Mabuhay City Homes	7.78 / 29.5	0.41	ABSENCE	ABSENCE	< 1
09/08/2020 11:50	S20-5793	Block 94 Lot 53, Guimaras St., Phase 1 Luxury, Mabuhay City Homes	7.88 / 28.8	0.35	ABSENCE	ABSENCE	< 1
09/08/2020 11:35	S20-5795	Block 134 Lot 22, Phase 2, Mabuhay City Homes	7.80 / 27.0	0.50	ABSENCE	ABSENCE	180
09/08/2020 14:55	S20-5801	Block 222 Lot 20, Mabuhay Ave, Phase 2, Mabuhay City Homes	7.30 / 27.4	0.38	ABSENCE	ABSENCE	< 1
09/10/2020 14:10	S20-5946	Water Pump, Joshua St., Phase 5, Mabuhay City Homes	7.68 / 29.0	0.36	ABSENCE	ABSENCE	-
09/10/2020 14:21	S20-5947	Block 31 Lot 134, Joshua St., Phase 5, Mabuhay City Homes	7.60 / 28.9	0.28	ABSENCE	ABSENCE	-
09/08/2020 11:10	S20-5790	Water Pump, Block 22 Lot 70, Phase 3 Luxury, Mabuhay City	7.44 / 29.1	1.06	ABSENCE	ABSENCE	< 1
09/08/2020 11:40	S20-5791	Block 19 Lot 13, Malang St., Phase 3 Luxury, Mabuhay City Homes	7.30 / 29.0	0.76	ABSENCE	ABSENCE	< 1
09/10/2020 14:59	S20-5948	Water Pump, Panganig St., Phase 3, Mabuhay City Homes	7.80 / 27.9	0.45	ABSENCE	ABSENCE	-
09/10/2020 15:10	S20-5949	Block 1 Lot 17, Dizon St., Phase 3, Mabuhay City Homes	7.77 / 29.5	0.36	ABSENCE	ABSENCE	-

NOT VALID WITHOUT QR CODE



REVIEWED BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
09/08/2020 12:10	S20-5796	Water Pump, Phase 1E Mabuhay Executive	7.86 / 28.9	0.50	ABSENCE	ABSENCE	< 1
09/08/2020 12:28	S20-5797	Block 236 Lot 9, Phase 1E Mabuhay Executive	7.65 / 29.9	0.44	ABSENCE	ABSENCE	< 1
BRGY. PULO							
09/10/2020 11:30	S20-5937	Water Pump, Block 12 Lot 22, Cabuyao Central	7.38 / 27.9	0.15	ABSENCE	ABSENCE	-
09/10/2020 11:41	S20-5938	Clubhouse, Narra Avenue, Cabuyao Central	7.40 / 28.0	0.10	ABSENCE	ABSENCE	-
09/10/2020 12:15	S20-5939	Water Pump, Block 11, Willow Park Homes	7.80 / 29.0	0.80	ABSENCE	ABSENCE	-
09/10/2020 12:22	S20-5940	Clubhouse, Willow Park Homes	7.65 / 28.6	0.40	ABSENCE	ABSENCE	-

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: **A** – Electrometric; **B** – Colorimetric; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR CODE



REVIEWED BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis