

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE I

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 23

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 05/04/2021 – 05/07/2021

| DATE/TIME COLLECTED | SAMPLE CODE | SAMPLE LOCATION | PARAMETER | | | | |
|--------------------------|-------------|--|---|---|-----------------------|---------|------------------------------|
| | | | pH/ Temperature ^A (- / °C) MDL: NA LOQ: NA | RESIDUAL CHLORINE ^B (mg/L) MDL: 0.06 LOQ: 0.20 | COLIFORM ^C | | HPC ^D (CFU/mL) |
| | | | TOTAL (Coliforms/ 100mL) | FECAL/ <i>E. coli</i> (Coliforms/ 100 mL) | | | |
| BRGY. BANAY-BANAY | | | | | | | |
| 05/04/2021 11:32 | S21-3261 | Water Pump, Block 63, Lakeside Nest Subdivision | - | 0.56 | ABSENCE | ABSENCE | < 1 |
| 05/04/2021 11:19 | S21-3262 | Block 12, Lot 5, Phase 4, Lakeside Nest Subdivision | - | 0.32 | ABSENCE | ABSENCE | 3 |
| BRGY. BANLIC | | | | | | | |
| 05/06/2021 12:13 | S21-3353 | Water Pump, Gran Seville Subdivision | 7.49 / 30.9 | 0.12 | ABSENCE | ABSENCE | - |
| 05/06/2021 12:37 | S21-3354 | Gate Entrance, Gran Seville Subdivision | 7.60 / 30.7 | 0.08 | ABSENCE | ABSENCE | - |
| BRGY. BIGAA | | | | | | | |
| 05/04/2021 14:32 | S21-3263 | #253 Elsol Subdivision | - | 0.69 | ABSENCE | ABSENCE | 2 |
| BRGY. GULOD | | | | | | | |
| 05/04/2021 16:10 | S21-3283 | Water Pump, Block 12, Noah St., Celestine Ville | 7.48 / 26.8 | 0.25 | ABSENCE | ABSENCE | < 1 |
| 05/04/2021 16:16 | S21-3284 | Guardhouse, Celestine Ville | 7.49 / 27.5 | 0.28 | ABSENCE | ABSENCE | < 1 |
| BRGY. MARINIG | | | | | | | |
| 05/04/2021 13:58 | S21-3251 | Block 3 Lot 17, Phase 1, Celestine Homes | - | 0.74 | ABSENCE | ABSENCE | < 1 |
| 05/04/2021 13:45 | S21-3252 | Block 23, Lot 10, Phase 1, Celestine Homes | - | 1.06 | ABSENCE | ABSENCE | < 1 |
| 05/04/2021 13:26 | S21-3253 | Water Pump, Block 9, Carnation St., Phase 2, Celestine Homes | - | 0.65 | ABSENCE | ABSENCE | < 1 |
| 05/04/2021 13:32 | S21-3254 | Block 13 Lot 2, Phase 2, Celestine Homes | - | 0.69 | ABSENCE | ABSENCE | 5 |
| 05/04/2021 13:08 | S21-3255 | Water Pump, Block 25, Phase 3, Southville | - | 0.40 | ABSENCE | ABSENCE | 200 |
| 05/04/2021 12:58 | S21-3256 | Block 19 Lot 33, Phase 3, Southville | - | 0.54 | ABSENCE | ABSENCE | < 1 |

NOT VALID WITHOUT QR CODE



REVIEWED BY:

ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

| DATE/TIME COLLECTED | SAMPLE CODE | SAMPLE LOCATION | PARAMETER | | | | |
|-------------------------|-------------|---|---|---|--------------------------------|--|------------------------------|
| | | | pH/ Temperature ^A (- / °C) | RESIDUAL CHLORINE ^B (mg/L) | COLIFORM ^C | | HPC ^D (CFU/mL) |
| | | | | | TOTAL (Coliforms/ 100mL) | FECAL/ <i>E. coli</i> (Coliforms/ 100 mL) | |
| | | | MDL: NA LOQ: NA | MDL: 0.06 LOQ: 0.20 | | | |
| BRGY. NIUGAN | | | | | | | |
| 05/04/2021 14:52 | S21-3264 | Block 2 Lot 6, St. Francis Homes VI | - | 0.86 | ABSENCE | ABSENCE | < 1 |
| 05/04/2021 12:44 | S21-3258 | Block 40 Lot 132, Phase 8, Southville | - | 0.38 | ABSENCE | ABSENCE | < 1 |
| 05/04/2021 12:33 | S21-3257 | Water Pump, Block 42, Phase 8, Southville | - | 0.39 | ABSENCE | ABSENCE | < 1 |
| 05/04/2021 15:19 | S21-3260 | Block 47 Lot 101, Phase 10, Southville | - | 0.06 | ABSENCE | ABSENCE | < 1 |
| 05/04/2021 11:48 | S21-3259 | Water Pump, Block 54, Phase 10, Southville | - | 0.13 | ABSENCE | ABSENCE | < 1 |
| 05/04/2021 15:03 | S21-3265 | Water Pump, Niugan Elementary School | - | 0.92 | ABSENCE | ABSENCE | < 1 |
| BRGY. SALA | | | | | | | |
| 05/04/2021 14:13 | S21-3266 | Gate Entrance, Amaia Scapes | - | 0.35 | ABSENCE | ABSENCE | < 1 |
| BRGY. SAN ISIDRO | | | | | | | |
| 05/06/2021 09:39 | S21-3357 | Block 3 Lot 33, Multiland IV | 7.61 / 30.7 | 0.25 | ABSENCE | ABSENCE | - |
| 05/06/2021 09:10 | S21-3355 | Water Pump, San Isidro Heights Subdivision | 7.47 / 30.7 | 0.40 | ABSENCE | ABSENCE | - |
| 05/06/2021 09:17 | S21-3356 | Block 3 Lot 1, San Isidro Heights Subdivision | 7.55 / 30.3 | 0.37 | ABSENCE | ABSENCE | - |

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: HPC – Heterotrophic Plate Count; CFU – Colony Forming Units; MDL – Method Detection Limit; LOQ – Limit of Quantification; NA – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: A – Electrometric; B – Colorimetric; C – Enzyme Substrate; D – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR CODE



REVIEWED BY:

ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE II

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 22

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 05/04/2021 – 05/07/2021

| DATE/TIME COLLECTED | SAMPLE CODE | SAMPLE LOCATION | PARAMETER | | | | |
|----------------------|-------------|---|---|---|--------------------------------|--|------------------------------|
| | | | pH/ Temperature ^A (- / °C) | RESIDUAL CHLORINE ^B (mg/L) | COLIFORM ^C | | HPC ^D (CFU/mL) |
| | | | | | TOTAL (Coliforms/ 100mL) | FECAL/ <i>E. coli</i> (Coliforms/ 100 mL) | |
| | | | MDL: NA LOQ: NA | MDL: 0.06 LOQ: 0.20 | | | |
| BRGY. MAMATID | | | | | | | |
| 05/04/2021 15:34 | S21-3279 | Water Pump, Buena Rosario Subdivision | 7.50 / 27.1 | 0.08 | ABSENCE | ABSENCE | < 1 |
| 05/04/2021 15:52 | S21-3280 | Block 7 Lot 6, Buena Rosario Subdivision | 7.59 / 26.2 | 0.05 | ABSENCE | ABSENCE | < 1 |
| 05/04/2021 13:39 | S21-3273 | Water Pump, Block 101, Samar St., Phase 2, Mabuhay City Homes | 7.55 / 27.9 | 0.46 | ABSENCE | ABSENCE | < 1 |
| 05/04/2021 14:20 | S21-3275 | Water Pump, Block 141, Carmona St., Phase 2, Mabuhay City Homes | 7.40 / 27.2 | 0.32 | ABSENCE | ABSENCE | < 1 |
| 05/04/2021 10:39 | S21-3281 | Water Pump, Block 198, Galacia St., Phase 2, Mabuhay City Homes | 7.45 / 27.8 | 0.88 | ABSENCE | ABSENCE | < 1 |
| 05/04/2021 14:01 | S21-3274 | Block 95 Lot 57, Guimaras St., Phase 1 Luxury, Mabuhay City Homes | 7.56 / 27.1 | 0.30 | ABSENCE | ABSENCE | < 1 |
| 05/04/2021 14:39 | S21-3276 | Block 134 Lot 22, Phase 2, Mabuhay City Homes | 7.51 / 27.6 | 0.20 | ABSENCE | ABSENCE | < 1 |
| 05/04/2021 10:44 | S21-3282 | Block 222 Lot 20, Mabuhay Ave, Phase 2, Mabuhay City Homes | 7.55 / 27.8 | 0.68 | ABSENCE | ABSENCE | < 1 |
| 05/06/2021 10:33 | S21-3358 | Water Pump, Joshua St., Phase 5, Mabuhay City Homes | 7.65 / 29.7 | 0.22 | ABSENCE | ABSENCE | - |
| 05/06/2021 10:51 | S21-3359 | Block 31 Lot 134, Joshua St., Phase 5, Mabuhay City Homes | - | 0.19 | ABSENCE | ABSENCE | - |
| 05/04/2021 13:15 | S21-3271 | Water Pump, Block 22 Lot 70, Phase 3 Luxury, Mabuhay City | 7.48 / 27.1 | 0.35 | ABSENCE | ABSENCE | < 1 |
| 05/04/2021 13:25 | S21-3272 | Block 19 Lot 13, Phase 3 Luxury, Mabuhay City Homes | 7.59 / 26.6 | 0.26 | ABSENCE | ABSENCE | < 1 |
| 05/06/2021 10:01 | S21-3360 | Water Pump, Panganig St., Phase 3, Mabuhay City Homes | - | 0.30 | ABSENCE | ABSENCE | - |
| 05/06/2021 10:16 | S21-3361 | Block 1 Lot 17, Dizon St., Phase 3, Mabuhay City Homes | - | 0.27 | ABSENCE | ABSENCE | - |

NOT VALID WITHOUT QR CODE



REVIEWED BY:

ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

| DATE/TIME COLLECTED | SAMPLE CODE | SAMPLE LOCATION | PARAMETER | | | | |
|---------------------|------------------------|--|--|---|--------------------------------|--|------------------------------|
| | | | pH/ Temperature ^A (- / °C) | RESIDUAL CHLORINE ^B (mg/L) | COLIFORM ^C | | HPC ^D (CFU/mL) |
| | | | | | TOTAL (Coliforms/ 100mL) | FECAL/ <i>E. coli</i> (Coliforms/ 100 mL) | |
| MDL: NA LOQ: NA | MDL: 0.06 LOQ: 0.20 | | | | | | |
| 05/04/2021 15:05 | S21-3277 | Water Pump, Phase 1E Mabuhay Executive | 7.45 / 27.6 | 0.10 | ABSENCE | ABSENCE | < 1 |
| 05/04/2021 15:15 | S21-3278 | Block 236 Lot 9, Phase 1E Mabuhay Executive | 7.54 / 27.5 | 0.08 | ABSENCE | ABSENCE | < 1 |
| 05/06/2021 11:13 | S21-3362 | Water Pump, Phase 6A, Mabuhay City | - | 0.25 | ABSENCE | ABSENCE | - |
| 05/06/2021 11:40 | S21-3363 | Reyes Residence, Phase 6A, Mabuhay Executive | - | 0.18 | ABSENCE | ABSENCE | - |
| BRGY. PULO | | | | | | | |
| 05/06/2021 13:17 | S21-3349 | Water Pump, Block 12 Lot 22, Cabuyao Central | 7.66 / 30.1 | 0.10 | ABSENCE | ABSENCE | - |
| 05/06/2021 13:42 | S21-3350 | Clubhouse, Narra Avenue, Cabuyao Central | 7.44 / 29.6 | 0.07 | ABSENCE | ABSENCE | - |
| 05/06/2021 14:30 | S21-3351 | Water Pump, Block 11, Willow Park Homes | 7.60 / 30.7 | 0.08 | ABSENCE | ABSENCE | - |
| 05/06/2021 15:22 | S21-3352 | Clubhouse, Willow Park Homes | 7.49 / 30.9 | 0.12 | ABSENCE | ABSENCE | - |

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: **A** – Electrometric; **B** – Colorimetric; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR CODE



REVIEWED BY:

ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis