

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna
CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION (LAGUNA WATER)

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE I (CHO-1)

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 22

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 11/11/2020-11/18/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20	TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
BRGY. BANAY-BANAY							
11/11/2020 14:00	S20-7713	Water Pump, Block 63, Lakeside Nest Subdivision	7.87 / 27.6	0.12	ABSENCE	ABSENCE	< 1
11/11/2020 14:40	S20-7714	Block 12, Lot 5, Phase 4, Lakeside Nest Subdivision	7.65 / 28.1	0.13	ABSENCE	ABSENCE	20
BRGY. BANLIC							
11/11/2020 17:57	S20-7027	Water Pump, Gran Seville Subdivision	7.38 / 28.4	0.17	ABSENCE	ABSENCE	< 1
11/11/2020 18:05	S20-7028	Gate Entrance, Gran Seville Subdivision	7.40 / 28.9	0.10	ABSENCE	ABSENCE	3
BRGY. BIGAA							
11/11/2020 11:30	S20-7715	#253 Elsol Subdivision	7.46 / 27.9	0.85	ABSENCE	ABSENCE	< 1
BRGY. GULOD							
11/17/2020 15:06	S20-7819	Water Pump, Block 12, Noah St., Celestine Ville	-	0.13	ABSENCE	ABSENCE	< 1
11/16/2020 14:41	S20-7777	Guardhouse, Celestine Ville	-	0.07	ABSENCE	ABSENCE	< 1
BRGY. MARINIG							
11/16/2020 15:30	S20-7795	Block 3 Lot 17, Phase 1, Celestine Homes	7.17 / 29.0	0.21	ABSENCE	ABSENCE	< 1
11/11/2020 11:54	S20-7704	Block 23, Lot 10, Phase 1, Celestine Homes	7.85 / 29.0	0.12	ABSENCE	ABSENCE	< 1
11/11/2020 12:10	S20-7705	Water Pump, Block 9, Carnation St., Phase 2, Celestine Homes	7.86 / 28.9	0.77	ABSENCE	ABSENCE	< 1
11/11/2020 12:16	S20-7706	Block 13 Lot 2, Phase 2, Celestine Homes	7.56 / 27.8	0.60	ABSENCE	ABSENCE	< 1
11/11/2020 12:30	S20-7707	Water Pump, Block 25, Phase 3, Southville	7.78 / 29.3	0.65	ABSENCE	ABSENCE	< 1
11/11/2020 12:39	S20-7708	Block 19 Lot 33, Phase 3, Southville	7.86 / 27.6	0.48	ABSENCE	ABSENCE	9

NOT VALID WITHOUT QR CODE



REVIEWED BY:

ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
BRGY. NIUGAN							
11/11/2020 11:18	S20-7716	Block 2 Lot 6, St. Francis Homes	7.55 / 28.9	0.58	ABSENCE	ABSENCE	< 1
11/11/2020 13:10	S20-7710	Block 40 Lot 132, Phase 8, Southville	7.18 / 28.5	0.35	ABSENCE	ABSENCE	< 1
11/11/2020 13:00	S20-7709	Water Pump, Block 45, Phase 8	7.78 / 29.0	0.40	ABSENCE	ABSENCE	< 1
11/11/2020 13:45	S20-7712	Block 47 Lot 101, Phase 10, Southville	7.77 / 29.8	0.14	ABSENCE	ABSENCE	< 1
11/11/2020 13:29	S20-7711	Water Pump, Block 54, Phase 10, Southville	7.55 / 29.8	0.19	ABSENCE	ABSENCE	< 1
BRGY. SALA							
11/16/2020 15:18	S20-7778	Gate Entrance, Amaia Scapes	-	0.62	ABSENCE	ABSENCE	< 1
BRGY. SAN ISIDRO							
11/11/2020 16:36	S20-7031	Block 3 Lot 33, Multiland IV	7.47 / 28.2	0.22	ABSENCE	ABSENCE	< 1
11/11/2020 15:55	S20-7029	Water Pump, San Isidro Heights Subdivision	7.45 / 29.3	0.35	ABSENCE	ABSENCE	< 1
11/11/2020 16:12	S20-7030	Block 3 Lot 1, San Isidro Heights Subdivision	7.50 / 29.6	0.28	ABSENCE	ABSENCE	< 1

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.


METHODS: **A** – Electrometric; **B** – Colorimetric; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition


NOT VALID WITHOUT QR CODE



REVIEWED BY:


ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:


ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna
CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE II (CHO-2)

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 20

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 11/11/2020-11/21/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
BRGY. MAMATID							
11/19/2020 09:31	S20-7887	Water Pump, Buena Rosario Subdivision	-	0.39	ABSENCE	ABSENCE	< 1
11/19/2020 09:48	S20-7888	Block 7 Lot 6, Buena Rosario Subdivision	-	0.36	ABSENCE	ABSENCE	< 1
11/16/2020 13:03	S20-7766	Water Pump, Block 101, Samar St., Phase 2, Mabuhay City Homes	-	0.60	ABSENCE	ABSENCE	< 1
11/16/2020 14:10	S20-7768	Water Pump, Block 141, Carmona St., Phase 2, Mabuhay City Homes	-	0.97	ABSENCE	ABSENCE	5
11/16/2020 11:53	S20-7774	Water Pump, Block 198, Galacia St., Phase 2, Mabuhay City Homes	-	0.40	ABSENCE	ABSENCE	3
11/16/2020 13:57	S20-7767	Block 95 Lot 57, Guimaras St., Phase 1 Luxury, Mabuhay City Homes	-	0.11	ABSENCE	ABSENCE	58
11/16/2020 14:17	S20-7769	Block 134 Lot 22, Phase 2, Mabuhay City Homes	-	0.15	ABSENCE	ABSENCE	< 1
11/16/2020 12:01	S20-7775	Block 222 Lot 20, Mabuhay Ave, Phase 2, Mabuhay City Homes	-	0.45	ABSENCE	ABSENCE	< 1
11/11/2020 15:10	S20-7032	Water Pump, Joshua St., Phase 5, Mabuhay City Homes	7.45 / 29.3	0.32	ABSENCE	ABSENCE	< 1
11/11/2020 15:17	S20-7033	Block 31 Lot 134, Joshua St., Phase 5, Mabuhay City Homes	7.50 / 28.6	0.27	ABSENCE	ABSENCE	3
11/16/2020 11:24	S20-7764	Water Pump, Block 22 Lot 70, Phase 3 Luxury, Mabuhay City	-	0.14	ABSENCE	ABSENCE	< 1
11/16/2020 11:37	S20-7765	Block 19 Lot 13, Phase 3 Luxury, Mabuhay City Homes	-	0.66	ABSENCE	ABSENCE	< 1
11/11/2020 14:40	S20-7034	Water Pump, Panganig St., Phase 3, Mabuhay City Homes	7.43 / 29.3	0.30	ABSENCE	ABSENCE	< 1
11/11/2020 14:28	S20-7035	Block 1 Lot 17, Dizon St., Phase 3, Mabuhay City Homes	7.49 / 29.6	0.18	ABSENCE	ABSENCE	< 1

NOT VALID WITHOUT QR CODE



REVIEWED BY:

ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
11/16/2020 12:45	S20-7770	Water Pump, Phase 1E Mabuhay Executive	-	0.60	ABSENCE	ABSENCE	< 1
11/16/2020 12:51	S20-7771	Block 236 Lot 9, Phase 1E Mabuhay Executive	-	0.30	ABSENCE	ABSENCE	< 1
BRGY. PULO							
11/11/2020 16:59	S20-7023	Water Pump, Block 12 Lot 22, Cabuyao Central	7.41 / 28.6	0.08	ABSENCE	ABSENCE	< 1
11/11/2020 17:10	S20-7024	Clubhouse, Narra Avenue, Cabuyao Central	7.47 / 29.3	0.04	ABSENCE	ABSENCE	< 1
11/11/2020 17:29	S20-7025	Water Pump, Block 11, Willow Park Homes	7.47 / 28.7	0.05	ABSENCE	ABSENCE	< 1
11/11/2020 17:38	S20-7026	Clubhouse, Willow Park Homes	7.43 / 28.7	0.03	ABSENCE	ABSENCE	< 1

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.


METHODS: **A** – Electrometric; **B** – Colorimetric; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition


NOT VALID WITHOUT QR CODE



REVIEWED BY:


ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:


ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis