

DOH Accredited Testing Laboratory (04A-002-2123-LW-22); PNRI (RML No. Y04.04132.17) PRC Certificate of Authority to Operate No. 111 PNP (License No. PDD03-230616-04201)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME: LAGUNA AAAWATER CORPORATION

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE I

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 26

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 03/01/2021 - 03/26/2021

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER					
			pH/	RESIDUAL	COLIFORMC			
			Temperature ^A (- / °C) MDL: NA LOQ: NA	(mg/L) MDL: 0.06 LOQ: 0.20	TOTAL (Coliforms/ 100mL)	FECAL/ E. coli (Coliforms/ 100 mL)	HPC ^D (CFU/mL)	
BRGY. BANAY-BANA	Υ							
03/01/2021 12:00	S21-1573	Water Pump, Block 63, Lakeside Nest Subdivision	-	1.62	ABSENCE	ABSENCE	<1	
03/01/2021 12:21	S21-1574	Block 12, Lot 5, Phase 4, Lakeside Nest Subdivision	-	1.77	ABSENCE	ABSENCE	<1	
BRGY. BANLIC								
03/02/2021 13:38	S21-1619	Water Pump, Gran Seville Subdivision	7.61 / 30.4	0.10	ABSENCE	ABSENCE	<1	
03/02/2021 13:44	S21-1620	Gate Entrance, Gran Seville Subdivision	7.55 / 29.6	0.04	ABSENCE	ABSENCE	< 1	
BRGY. BIGAA								
03/01/2021 13:15	S21-1575	#253 Elsol Subdivision	-	0.43	ABSENCE	ABSENCE	<1	
BRGY. GULOD								
03/02/2021 13:25	S21-1644	Water Pump, Block 12, Noah St., Celestine Ville	7.68 / 27.1	0.40	ABSENCE	ABSENCE	<1	
03/02/2021 13:40	S21-1645	Guardhouse, Celestine Ville	7.60 / 27.3	0.36	ABSENCE	ABSENCE	<1	
BRGY. MARINIG								
03/01/2021 10:22	S21-1563	Block 3 Lot 17, Phase 1, Celestine Homes		1.17	ABSENCE	ABSENCE	<1	
03/01/2021 10:59	S21-1564	Block 23, Lot 10, Phase 1, Celestine Homes		1.35	ABSENCE	ABSENCE	<1	
03/01/2021 10:42	S21-1565	Water Pump, Block 9, Carnation St., Phase 2, Celestine Homes	-	1.24	ABSENCE	ABSENCE	<1	
03/01/2021 10:49	S21-1566	Block 13 Lot 2, Phase 2, Celestine Homes	-	1.09	ABSENCE	ABSENCE	<1	
03/01/2021 11:15	S21-1567	Water Pump, Block 25, Phase 3, Southville		0.69	ABSENCE	ABSENCE	33	
03/01/2021 11:23	S21-1568	Block 19 Lot 33, Phase 3, Southville		0.95	ABSENCE	ABSENCE	<1	

NOT VALID WITHOUT QR CODE

REVIEWED BY:

CERTIFIED CORRECT BY:

ALYSSA MARIE C. PENALES, RMT Microbiology Unit Manager (OIC) License No(s). (PRC 0064969)

Laborator Services Manager License No. (FRC 0060968)

ANNA KAR



DOH Accredited Testing Laboratory (04A-002-2123-LW-22); PNRI (RML No. Y04.04132.17) PRC Certificate of Authority to Operate No. 111 PNP (License No. PDD03-230616-04201)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER					
			pH/	RESIDUAL CHLORINEB (mg/L) MDL: 0.06 LOQ: 0.20	COLIFORMC			
			Temperature ^A (- / °C) MDL: NA LOQ: NA		TOTAL (Coliforms/ 100mL)	FECAL/ E. coli (Coliforms/ 100 mL)	HPC ^D (CFU/mL	
BRGY. NIUGAN								
03/01/2021 12:57	S21-1576	Block 2 Lot 6, St. Francis Homes		0.62	ABSENCE	ABSENCE	<1	
03/01/2021 11:36	S21-1570	Block 40 Lot 132, Phase 8, Southville	-	0.53	ABSENCE	ABSENCE	4	
03/01/2021 11:43	S21-1569	Water Pump, Block 45, Phase 8, Southville		0.51	ABSENCE	ABSENCE	<1	
03/01/2021 12:00	S21-1572	Block 47 Lot 101, Phase 10, Southville	-	0.14	ABSENCE	ABSENCE	<1	
03/01/2021 11:55	S21-1571	Water Pump, Block 54, Phase 10, Southville	-	0.31	ABSENCE	ABSENCE	1	
03/01/2021 12:49	S21-1577	Water Pump, Niugan Elementary School	-	0.79	ABSENCE	ABSENCE	70	
BRGY. SALA								
03/01/2021 10:07	S21-1578	Gate Entrance, Amaia Scapes	-	0.30	ABSENCE	ABSENCE	<1	
BRGY. SAN ISIDRO								
03/02/2021 12:27	S21-1623	Block 3 Lot 33, Multiland IV	7.51 / 29.8	0.15	ABSENCE	ABSENCE	<1	
03/24/2021 11:20	\$21-2296	Block 2 Lot 32, Multiland IV	7.60 / 29.6	0.32	ABSENCE	ABSENCE	<1	
03/02/2021 12:01	S21-1621	Water Pump, San Isidro Heights Subdivision	7.62 / 30.7	0.37	ABSENCE	ABSENCE	<1	
03/02/2021 12:11	S21-1622	Block 3 Lot 1, San Isidro Heights Subdivision	7.44 / 29.7	0.25	ABSENCE	ABSENCE	<1	
03/24/2021 11:07	S21-2294	Water Pump, San Isidro Homes	7.41 / 28.5	1.60	ABSENCE	ABSENCE	4	
03/24/2021 11:49	S21-2295	City Water, Canaan Homes	7.72 / 28.3	0.03	ABSENCE	ABSENCE	340	

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: <u>HPC</u> – Heterotrophic Plate Count; <u>CFU</u> – Colony Forming Units; <u>MDL</u> – Method Detection Limit; <u>LOQ</u> – Limit of Quantification; <u>NA</u> – Not Applicable **DEVIATIONS:** No deviation noted on sample collection and submission.

METHODS: A - Electrometric; B - Colorimetric; C- Enzyme Substrate; D - Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR CODE

REVIEWED BY:

ALYSSA MARIE C. PENALES, RMT Microbiology Unit Manager (OIC) License No(s). (PRC 0064969) **CERTIFIED CORRECT BY:**

ANNA KARLAS. GUTIERREZ, RMT Laboratory Services Manager License No(s). (PRC 0060968)



DOH Accredited Testing Laboratory (04A-002-2123-LW-22); PNRI (RML No. Y04.04132.17) PRC Certificate of Authority to Operate No. 111 PNP (License No. PDD03-230616-04201)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME: LAGUNA AAAWATER CORPORATION

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE II

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 22

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 03/02/2021 - 03/04/2021

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER					
			pH/	RESIDUAL	COLIFORMC			
			Temperature ^A (- / °C) MDL: NA LOQ: NA	CHLORINE ^B (mg/L) MDL: 0.06 LOQ: 0.20	TOTAL (Coliforms/ 100mL)	FECAL/ E. coli (Coliforms/ 100 mL)	HPC ^D (CFU/mL)	
BRGY. MAMATID			1000.1111	204.0.20				
03/02/2021 12:00	S21-1640	Water Pump, Buena Rosario Subdivision	7.59 / 27.6	0.48	ABSENCE	ABSENCE	<1	
03/02/2021 12:18	521-1641	Block 7 Lot 6, Buena Rosario Subdivision	7.61 / 28.1	0.45	ABSENCE	ABSENCE	<1	
03/02/2021 10:18	S21-1634	Water Pump, Block 101, Samar St., Phase 2, Mabuhay City Homes	7.65 / 28.1	0.41	ABSENCE	ABSENCE	<1	
03/02/2021 10:45	S21-1636	Water Pump, Block 141, Carmona St., Phase 2, Mabuhay City Homes	7.61 / 27.5	0.25	ABSENCE	ABSENCE	<1	
03/02/2021 12:40	S21-1642	Water Pump, Block 198, Galacia St., Phase 2, Mabuhay City Homes	7.48 / 28.6	0.26	ABSENCE	ABSENCE	<1	
03/02/2021 10:28	S21-1635	Block 95 Lot 57, Guimaras St., Phase 1 Luxury, Mabuhay City Homes	7.59 / 27.1	0.36	ABSENCE	ABSENCE	<1	
03/02/2021 10:59	S21-1637	Block 134 Lot 22, Phase 2, Mabuhay City Homes	7.62 / 28.1	0.21	ABSENCE	ABSENCE	<1	
03/02/2021 12:58	S21-1643	Block 222 Lot 20, Mabuhay Ave, Phase 2, Mabuhay City Homes	7.41 / 27.3	0.12	ABSENCE	ABSENCE	<1	
03/02/2021 11:18	S21-1624	Water Pump, Joshua St., Phase 5, Mabuhay City Homes	7.52 / 30.8	0.25	ABSENCE	ABSENCE	<1	
03/02/2021 11:39	S21-1625	Block 31 Lot 134, Joshua St., Phase 5, Mabuhay City Homes	7.52 / 30.1	0.22	ABSENCE	ABSENCE	<1	
03/02/2021 09:41	S21-1632	Water Pump, Block 22 Lot 70, Phase 3 Luxury, Mabuhay City	7.51 / 27.8	0.58	ABSENCE	ABSENCE	<1	
03/02/2021 09:55	S21-1633	Block 19 Lot 13, Phase 3 Luxury, Mabuhay City Homes	7.55 / 27.6	0.36	ABSENCE	ABSENCE	<1	
03/02/2021 09:20	S21-1626	Water Pump, Panganig St., Phase 3, Mabuhay City Homes	7.42 / 29.7	0.36	ABSENCE	ABSENCE	<1	
03/02/2021 09:42	S21-1627	Block 1 Lot 17, Dizon St., Phase 3, Mabuhay City Homes	7.32 / 30.6	0.32	ABSENCE	ABSENCE	<1	

NOT VALID WITHOUT QR CODE

REVIEWED BY:

CERTIFIED CORRECT BY:

ALYSSA MARIE C. PENALES, RMT Microbiology Unit Manager (OIC) License No(s). (PRC 0064969)

Laboratory Services Manager

License No(s). (PRC 006/968)

ANNA KARLA'S GUTIERREZ, RMT



DOH Accredited Testing Laboratory (04A-002-2123-LW-22); PNRI (RML No. Y04.04132.17) PRC Certificate of Authority to Operate No. 111 PNP (License No. PDD03-230616-04201)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER					
			pH/	RESIDUAL	COLIFORMC			
			Temperature ^A (- / °C)	(Coliforn	TOTAL (Coliforms/	FECAL/ E. coli (Coliforms/ 100 mL)	HPC ^D (CFU/mL)	
			MDL: NA LOQ: NA		100mL)			
03/02/2021 11:06	S21-1638	Water Pump, Phase 1E Mabuhay Executive	7.66 / 27.9	0.08	ABSENCE	ABSENCE	<1	
03/02/2021 11:27	S21-1639	Block 236 Lot 9, Phase 1E Mabuhay Executive	7.65 / 28.0	0.07	ABSENCE	ABSENCE	<1	
03/02/2021 10:13	S21-1628	Water Pump, Phase 6A, Mabuhay City	7.42 / 30.3	0.30	ABSENCE	ABSENCE	<1	
03/02/2021 10:21	S21-1629	De Guzman Residence, Phase 6A, Mabuhay Executive	7.31 / 29.6	0.27	ABSENCE	ABSENCE	<1	
BRGY. PULO								
03/02/2021 12:50	S21-1615	Water Pump, Block 12 Lot 22, Cabuyao Central	7.52 / 29.6	0.08	ABSENCE	ABSENCE	<1	
03/02/2021 13:01	S21-1616	Clubhouse, Narra Avenue, Cabuyao Central	7.49 / 30.7	0.05	ABSENCE	ABSENCE	<1	
03/02/2021 13:11	S21-1617	Water Pump, Block 11, Willow Park Homes	7.51 / 30.4	0.07	ABSENCE	ABSENCE	<1	
03/02/2021 13:24	S21-1618	Clubhouse, Willow Park Homes	7.44 / 30.7	0.04	ABSENCE	ABSENCE	<1	

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: <u>HPC</u> – Heterotrophic Plate Count; <u>CFU</u> – Colony Forming Units; <u>MDL</u> – Method Detection Limit; <u>LOQ</u> – Limit of Quantification; <u>NA</u> – Not Applicable **DEVIATIONS:** No deviation noted on sample collection and submission.

METHODS: A - Electrometric; B - Colorimetric; C- Enzyme Substrate; D - Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR CODE

REVIEWED BY:

ALYSSA MARIÈ PENALES, RMT Microbiology Unit Manager (OIC) License No(s). (PRC 0064969) **CERTIFIED CORRECT BY:**

ANNA KARLA S'GUTIERREZ, RMT Laboratory Services Manager License No(s), (PRC 0060968)