

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE I

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 23

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 07/05/2021 – 07/14/2021

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
BRGY. BANAY-BANAY							
07/05/2021 10:26	S21-4695	Water Pump, Block 63, Lakeside Nest Subdivision	-	0.79	ABSENCE	ABSENCE	< 1
07/05/2021 10:11	S21-4696	Block 12, Lot 5, Phase 4, Lakeside Nest Subdivision	-	0.65	ABSENCE	ABSENCE	< 1
BRGY. BANLIC							
07/12/2021 12:44	S21-4983	Water Pump, Gran Seville Subdivision	7.44 / 29.7	0.17	ABSENCE	ABSENCE	17
07/12/2021 13:15	S21-4984	Gate Entrance, Gran Seville Subdivision	7.41 / 30.1	0.15	ABSENCE	ABSENCE	< 1
BRGY. BIGAA							
07/05/2021 13:09	S21-4697	#253 Elsol Subdivision	-	0.77	ABSENCE	ABSENCE	< 1
BRGY. GULOD							
07/05/2021 13:48	S21-4717	Water Pump, Block 12, Noah St., Celestine Ville	7.51 / 28.1	0.25	ABSENCE	ABSENCE	1
07/05/2021 13:59	S21-4718	Guardhouse, Celestine Ville	7.55 / 27.6	0.19	ABSENCE	ABSENCE	< 1
BRGY. MARINIG							
07/05/2021 12:35	S21-4685	Block 3 Lot 17, Phase 1, Celestine Homes	-	0.12	ABSENCE	ABSENCE	< 1
07/05/2021 12:26	S21-4686	Block 23, Lot 10, Phase 1, Celestine Homes	-	0.16	ABSENCE	ABSENCE	< 1
07/05/2021 12:12	S21-4687	Water Pump, Block 9, Carnation St., Phase 2, Celestine Homes	-	0.51	ABSENCE	ABSENCE	< 1
07/05/2021 12:18	S21-4688	Block 13 Lot 2, Phase 2, Celestine Homes	-	0.54	ABSENCE	ABSENCE	< 1
07/05/2021 11:51	S21-4689	Water Pump, Block 25, Phase 3, Southville	-	0.58	ABSENCE	ABSENCE	130
07/05/2021 11:43	S21-4690	Block 19 Lot 33, Phase 3, Southville	-	0.55	ABSENCE	ABSENCE	< 1

NOT VALID WITHOUT QR CODE



REVIEWED BY:

ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20	TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
BRGY. NIUGAN							
07/05/2021 13:22	S21-4698	Block 2 Lot 6, St. Francis Homes VI	-	0.17	ABSENCE	ABSENCE	< 1
07/05/2021 11:27	S21-4692	Block 40 Lot 132, Phase 8, Southville	-	1.45	ABSENCE	ABSENCE	< 1
07/05/2021 11:15	S21-4691	Water Pump, Block 42, Phase 8, Southville	-	0.85	ABSENCE	ABSENCE	40
07/05/2021 11:02	S21-4694	Block 47 Lot 101, Phase 10, Southville	-	0.37	ABSENCE	ABSENCE	< 1
07/05/2021 10:52	S21-4693	Water Pump, Block 54, Phase 10, Southville	-	0.20	ABSENCE	ABSENCE	2
07/12/2021 10:26	S21-4978	Water Pump, Niugan Elementary School	7.39 / 29.8	0.51	ABSENCE	ABSENCE	< 1
BRGY. SALA							
07/05/2021 12:50	S21-4700	Gate Entrance, Amaia Scapes	-	1.02	ABSENCE	ABSENCE	< 1
BRGY. SAN ISIDRO							
07/12/2021 14:18	S21-4987	Block 3 Lot 33, Multiland IV	7.55 / 30.7	0.27	ABSENCE	ABSENCE	< 1
07/12/2021 13:39	S21-4985	Water Pump, San Isidro Heights Subdivision	7.42 / 29.8	0.34	ABSENCE	ABSENCE	3
07/12/2021 14:01	S21-4986	Block 3 Lot 1, San Isidro Heights Subdivision	7.61 / 29.7	0.30	ABSENCE	ABSENCE	8

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: **A** – Electrometric; **B** – Colorimetric; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR CODE



REVIEWED BY:

ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna
CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE II

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 24

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 07/05/2021 – 07/14/2021

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
BRGY. MAMATID							
07/05/2021 12:28	S21-4713	Water Pump, Buena Rosario Subdivision	7.36 / 28.5	0.09	ABSENCE	ABSENCE	3
07/05/2021 12:39	S21-4714	Block 7 Lot 6, Buena Rosario Subdivision	7.41 / 27.0	0.07	ABSENCE	ABSENCE	2
07/05/2021 11:13	S21-4707	Water Pump, Block 101, Samar St., Phase 2, Mabuhay City Homes	7.38 / 28.5	0.41	ABSENCE	ABSENCE	5
07/05/2021 11:20	S21-4709	Water Pump, Block 141, Carmona St., Phase 2, Mabuhay City Homes	7.51 / 27.1	0.45	ABSENCE	ABSENCE	< 1
07/05/2021 13:15	S21-4715	Water Pump, Block 198, Galacia St., Phase 2, Mabuhay City Homes	7.44 / 27.6	0.20	ABSENCE	ABSENCE	< 1
07/05/2021 11:18	S21-4708	Block 95 Lot 57, Guimaras St., Phase 1 Luxury, Mabuhay City Homes	7.40 / 28.6	0.36	ABSENCE	ABSENCE	4
07/05/2021 11:39	S21-4710	Block 134 Lot 22, Phase 2, Mabuhay City Homes	7.48 / 28.2	0.35	ABSENCE	ABSENCE	4
07/05/2021 13:24	S21-4716	Block 222 Lot 20, Mabuhay Ave, Phase 2, Mabuhay City Homes	7.43 / 27.6	0.28	ABSENCE	ABSENCE	< 1
07/12/2021 09:20	S21-4988	Water Pump, Joshua St., Phase 5, Mabuhay City Homes	7.41 / 30.1	0.41	ABSENCE	ABSENCE	< 1
07/12/2021 09:45	S21-4989	Block 31 Lot 134, Joshua St., Phase 5, Mabuhay City Homes	7.67 / 29.7	0.27	ABSENCE	ABSENCE	5
07/05/2021 10:40	S21-4705	Water Pump, Block 22 Lot 70, Phase 3 Luxury, Mabuhay City	7.48 / 27.5	0.45	ABSENCE	ABSENCE	3
07/05/2021 10:50	S21-4706	Block 19 Lot 13, Phase 3 Luxury, Mabuhay City Homes	7.51 / 27.6	0.36	ABSENCE	ABSENCE	3
07/12/2021 10:38	S21-4990	Water Pump, Panganig St., Phase 3, Mabuhay City Homes	7.61 / 29.6	0.32	ABSENCE	ABSENCE	87
07/12/2021 10:59	S21-4991	Block 1 Lot 17, Dizon St., Phase 3, Mabuhay City Homes	7.55 / 29.6	0.30	ABSENCE	ABSENCE	< 1

NOT VALID WITHOUT QR CODE



REVIEWED BY:

ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
07/05/2021 11:55	S21-4711	Water Pump, Phase 1E Mabuhay Executive	7.40 / 28.8	0.12	ABSENCE	ABSENCE	2
07/05/2021 12:18	S21-4712	Block 236 Lot 9, Phase 1E Mabuhay Executive	7.38 / 27.6	0.11	ABSENCE	ABSENCE	< 1
07/12/2021 10:12	S21-4992	Water Pump, Phase 6A, Mabuhay City	7.61 / 29.8	0.15	ABSENCE	ABSENCE	3
07/12/2021 10:20	S21-4993	Gomez Residence, Phase 6A, Mabuhay Executive	7.61 / 29.7	0.10	ABSENCE	ABSENCE	3
07/05/2021 14:18	S21-4719	9001,Block 252, Mabuhay City Subdivision	7.45 / 28.1	0.36	ABSENCE	ABSENCE	< 1
07/05/2021 14:33	S21-4720	Clubhouse, Block 252, Mabuhay City Subdivision	7.48 / 27.6	0.30	ABSENCE	ABSENCE	< 1
BRGY. PULO							
07/12/2021 11:17	S21-4979	Water Pump, Block 12 Lot 22, Cabuyao Central	7.55 / 29.6	0.12	ABSENCE	ABSENCE	88
07/12/2021 11:34	S21-4980	Clubhouse, Narra Avenue, Cabuyao Central	7.61 / 30.1	0.10	ABSENCE	ABSENCE	< 1
07/12/2021 11:56	S21-4981	Water Pump, Block 11, Willow Park Homes	7.49 / 29.3	0.15	ABSENCE	ABSENCE	< 1
07/12/2021 12:14	S21-4982	Clubhouse, Willow Park Homes	7.51 / 29.8	0.13	ABSENCE	ABSENCE	< 1

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: **A** – Electrometric; **B** – Colorimetric; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR CODE



REVIEWED BY:

ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis