

**ADDRESS:** 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna  
**CONTACT NO.:** (049) 543-1916  
**WEBSITE:** [www.lagunawater.com.ph](http://www.lagunawater.com.ph)

**CUSTOMER NAME :** LAGUNA AAAWATER CORPORATION (LAGUNA WATER)

**ADDRESS :** G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

**ATTENTION :** SANTA ROSA CITY HEALTH OFFICE I (CHO-1)

### SUMMARY OF LABORATORY ANALYSIS

**NO. OF SAMPLES :** 20

**TOTAL PARAMETERS TESTED :** 5

**ANALYSIS DATE(S) :** 06/02/2020-07/01/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature <sup>A</sup> (- / °C)  MDL: NA LOQ: NA	RESIDUAL CHLORINE <sup>B</sup> (mg/L)  MDL: 0.06 LOQ: 0.20	COLIFORM <sup>C</sup>		HPC <sup>D</sup> (CFU/mL)
TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)						
<b>BRGY. BIÑAN</b>							
06/02/2020 11:19	S20-3503	Laguna Wellfield 1	7.40 / 28.0	0.32	ABSENCE	ABSENCE	< 1
<b>BRGY. CAINGIN</b>							
06/15/2020 13:03	S20-3782	Water Pump, Block 57, Phase 1, Southville	8.12 / 31.5	0.33	ABSENCE	ABSENCE	-
06/15/2020 13:25	S20-3783	Block 25 Lot 7, Phase 3, Southville	8.11 / 31.1	0.39	ABSENCE	ABSENCE	-
<b>BRGY. KANLURAN</b>							
06/15/2020 11:58	S20-3779	Gate Entrance, Alfonso Homes I	7.82 / 37.1	0.82	ABSENCE	ABSENCE	-
06/15/2020 11:50	S20-3777	#621 Rizal Boulevard	7.86 / 32.4	0.68	ABSENCE	ABSENCE	-
<b>BRGY. MALUSAK</b>							
06/15/2020 11:45	S20-3778	Santa Rosa City Hall	8.07 / 32.6	0.65	ABSENCE	ABSENCE	-
<b>BRGY. MARKET AREA</b>							
06/15/2020 11:09	S20-3776	Source, Market Area	7.92 / 31.5	0.66	ABSENCE	ABSENCE	-
<b>BRGY. SINALHAN</b>							
06/15/2020 10:49	S20-3775	Block 8 Lot 16, Bayshore III	8.16 / 32.2	0.57	ABSENCE	ABSENCE	-
06/15/2020 10:26	S20-3774	Amoranto Compound, Phase 2, Sinalhan	7.98 / 31.6	0.42	ABSENCE	ABSENCE	-
<b>BRGY. TAGAPO</b>							
06/29/2020 11:28	S20-4293	#60 31 JP Rizal Boulevard	7.16 / 29.1	0.22	ABSENCE	ABSENCE	< 1
06/29/2020 12:07	S20-4295	Block 1 Lot 18, Fairfield of Margana Subdivision	7.22 / 29.8	0.48	ABSENCE	ABSENCE	1

NOT VALID WITHOUT QR CODE



REVIEWED BY:

JETHRO D. ESCOBIN  
Microbiology Unit Manager

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT  
Laboratory Services Manager  
License No(s). (PRC 0060968)

*This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis*

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna  
CONTACT NO.: (049) 543-1916  
WEBSITE: [www.lagunawater.com.ph](http://www.lagunawater.com.ph)

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature <sup>A</sup> (- / °C)	RESIDUAL CHLORINE <sup>B</sup> (mg/L)	COLIFORM <sup>C</sup>		HPC <sup>D</sup> (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20						
06/29/2020 11:41	S20-4303	Water Pump, Rosewood Homes I	7.07 / 29.1	0.58	ABSENCE	ABSENCE	1
06/29/2020 11:50	S20-4304	Block 3 Lot 31, Rosewood Homes I	7.26 / 29.3	0.43	ABSENCE	ABSENCE	< 1
06/29/2020 12:15	S20-4305	Block 4 Lot 1, Rosewood Homes II	7.18 / 29.0	0.43	ABSENCE	ABSENCE	2
06/29/2020 13:57	S20-4294	Block 2 Lot 50, Buena Rosa 1 Subdivision	7.44 / 28.8	0.40	ABSENCE	ABSENCE	2
06/29/2020 14:29	S20-4306	Water Pump, Buena Rosa 10 Subdivision	7.31 / 29.3	0.66	ABSENCE	ABSENCE	4
06/29/2020 13:32	S20-4297	Cistern Tank, SM Sta. Rosa	7.49 / 31.0	0.07	ABSENCE	ABSENCE	290
06/29/2020 15:39	S20-4298	Admin Pantry, SM Sta. Rosa	7.56 / 29.1	0.05	ABSENCE	ABSENCE	72
06/29/2020 13:07	S20-4299	Cistern Tank, Robinson's Mall	7.31 / 29.8	0.03	ABSENCE	ABSENCE	12
06/29/2020 13:13	S20-4300	Paotsin, Robinson's Mall	7.41 / 29.6	0.03	ABSENCE	ABSENCE	16

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: HPC – Heterotrophic Plate Count; CFU – Colony Forming Units; MDL – Method Detection Limit; LOQ – Limit of Quantification; NA – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: A – Electrometric; B – Colorimetric; C – Enzyme Substrate; D – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23<sup>rd</sup> Edition


NOT VALID WITHOUT QR CODE



REVIEWED BY:

  
JETHRO D. ESCOBIN  
Microbiology Unit Manager

CERTIFIED CORRECT BY:

  
ANNA KARLA S. GUTIERREZ, RMT  
Laboratory Services Manager  
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna  
CONTACT NO.: (049) 543-1916  
WEBSITE: [www.lagunawater.com.ph](http://www.lagunawater.com.ph)

**CUSTOMER NAME : LAGUNA AAAWATER CORPORATION (LAGUNA WATER)**

**ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna**

**ATTENTION : SANTA ROSA CITY HEALTH OFFICE II (CHO-2)**

### SUMMARY OF LABORATORY ANALYSIS

**NO. OF SAMPLES : 48**

**TOTAL PARAMETERS TESTED : 5**

**ANALYSIS DATE(S) : 06/02/2020-07/01/2020**

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature <sup>A</sup> (- / °C)  MDL: NA LOQ: NA	RESIDUAL CHLORINE <sup>B</sup> (mg/L)  MDL: 0.06 LOQ: 0.20	COLIFORM <sup>C</sup>		HPC <sup>D</sup> (CFU/mL)
TOTAL		FECAL/ <i>E. coli</i>					
(Coliforms/ 100mL)		(Coliforms/ 100 mL)					
<b>BRGY. BIÑAN</b>							
06/02/2020 11:19	S20-3503	Laguna Wellfield 1	7.40 / 28.0	0.32	ABSENCE	ABSENCE	< 1
<b>BRGY. BALIBAGO</b>							
06/29/2020 14:56	S20-4292	#1354 Facundo Compound	7.28 / 29.1	0.54	ABSENCE	ABSENCE	4
06/17/2020 11:34	S20-3873	Clubhouse, South Hampton	8.13 / 30.2	0.40	ABSENCE	ABSENCE	< 1
06/17/2020 11:49	S20-3874	Clubhouse, South Hampton	8.11 / 30.6	0.40	ABSENCE	ABSENCE	< 1
<b>BRGY. DILA</b>							
06/17/2020 13:08	S20-3887	Water Pump, Phase 3E, Mabuhay Homes 2000	7.63 / 31.5	0.22	ABSENCE	ABSENCE	< 1
06/17/2020 13:16	S20-3888	Block 2 Lot 10, Mabuhay Homes 2000	7.64 / 30.4	0.30	ABSENCE	ABSENCE	< 1
06/17/2020 12:39	S20-3889	Water Pump, Block 12, Phase 2E, Mabuhay Homes 2000	7.68 / 28.9	0.04	ABSENCE	ABSENCE	5
06/17/2020 12:52	S20-3889	Block 34 Lot 9, Phase 2E, Mabuhay Homes 2000	7.89 / 28.9	0.04	ABSENCE	ABSENCE	90
<b>BRGY. DITA</b>							
06/17/2020 11:51	S20-3891	Block 24 Lot 2, New Santa Rosa Homes	7.96 / 30.2	0.03	ABSENCE	ABSENCE	210
06/17/2020 12:02	S20-3892	Block 19 Lot 11, New Santa Rosa Homes	8.18 / 30.8	0.02	ABSENCE	ABSENCE	100
06/17/2020 12:10	S20-3875	Water Pump, Block 4 Lot 32, San Lorenzo Royale	7.11 / 29.7	0.24	ABSENCE	ABSENCE	< 1
06/17/2020 12:23	S20-3876	Block 11 Lot 52, San Lorenzo Royale	7.16 / 30.7	0.18	ABSENCE	ABSENCE	< 1
06/17/2020 11:26	S20-3893	Water Tank, SolCar Ville Subdivision	7.54 / 29.0	0.23	ABSENCE	ABSENCE	< 1
06/17/2020 11:35	S20-3894	Block 3 Lot 7, SolCar Ville Subdivision	7.81 / 31.2	0.26	ABSENCE	ABSENCE	< 1

**NOT VALID WITHOUT QR CODE**



**REVIEWED BY:**

JETHRO D. ESCOBIN  
Microbiology Unit Manager

**CERTIFIED CORRECT BY:**

ANNA KARLA S. GUTIERREZ, RMT  
Laboratory Services Manager  
License No(s). (PRC 0060968)

*This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis.*

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: [www.lagunawater.com.ph](http://www.lagunawater.com.ph)

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature <sup>A</sup> (- / °C)	RESIDUAL CHLORINE <sup>B</sup> (mg/L)	COLIFORM <sup>C</sup>		HPC <sup>D</sup> (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
06/17/2020 12:17	S20-3895	#1780 National Road	7.81 / 29.1	0.04	ABSENCE	ABSENCE	370
06/17/2020 11:09	S20-3900	R & B Ice Plant, Inc.	6.76 / 30.6	0.02	ABSENCE	ABSENCE	320
<b>BRGY. DON JOSE</b>							
06/23/2020 12:59	S20-4021	Science High School, Phase 1, Laguna Bel-Air	7.02 / 27.4	0.85	ABSENCE	ABSENCE	< 1
06/23/2020 12:09	S20-4023	Church, Block 108, Phase 5, Laguna Bel-Air	6.38 / 31.0	0.13	ABSENCE	ABSENCE	8
06/23/2020 13:08	S20-4022	Block 34 Lot 59 Laguna Bel-Air I	6.93 / 29.0	0.90	ABSENCE	ABSENCE	1
06/23/2020 12:51	S20-4027	Block 47 Lot 12 Laguna Bel-Air IV	6.86 / 30.0	0.90	ABSENCE	ABSENCE	< 1
06/23/2020 14:02	S20-4015	8001, Pump 1, Acacia St., Santa Rosa Village I	7.16 / 26.9	0.51	ABSENCE	ABSENCE	-
06/23/2020 14:07	S20-4016	Clubhouse. Phase 4B, Santa Rosa Village I	7.10 / 30.7	0.49	ABSENCE	ABSENCE	< 1
06/23/2020 14:17	S20-4017	Clubhouse, Santa Rosa Village II	7.09 / 29.4	0.35	ABSENCE	ABSENCE	1
06/23/2020 13:50	S20-4018	Pump 9 & 10, Santa Rosa Estates I	7.12 / 27.5	0.39	ABSENCE	ABSENCE	16
06/23/2020 13:44	S20-4019	Clubhouse, Santa Rosa Estates I	7.21 / 29.3	0.42	ABSENCE	ABSENCE	110
<b>BRGY. MACABLING</b>							
06/29/2020 14:29	S20-4306	Water Pump, Buena Rosa 9 Subdivision	7.31 / 28.1	0.47	ABSENCE	ABSENCE	-
06/29/2020 14:28	S20-307	Block 4 Lot 44, Phase 1, Buena Rosa 9 Subdivision	7.38 / 29.6	0.58	ABSENCE	ABSENCE	2
06/29/2020 14:15	S20-4301	Water Pump, Corinthian Subdivision	7.43 / 29.2	0.46	ABSENCE	ABSENCE	32
06/29/2020 14:21	S20-4302	Block 11 Lot 19, Corinthian Subdivision	7.27 / 30.6	0.32	ABSENCE	ABSENCE	1
06/17/2020 13:45	S20-3898	Water Pump, Metrogate	7.98 / 29.4	0.48	ABSENCE	ABSENCE	4
06/17/2020 13:54	S20-3899	Gate Entrance, Metrogate	8.16 / 34.5	0.26	ABSENCE	ABSENCE	< 1
<b>BRGY. MALITLIT</b>							
06/17/2020 11:00	S20-3896	Clubhouse, Casan Residencia Subdivision	6.69 / 30.2	0.04	ABSENCE	ABSENCE	41
06/17/2020 13:21	S20-3877	Block 3 Lot 1, Phase 1A Annex, San Lorenzo Subd.	7.22 / 30.1	0.47	ABSENCE	ABSENCE	< 1
06/17/2020 13:32	S20-3878	Block 5 Lot 25, Phase 1A Annex, San Lorenzo Subd.	7.24 / 30.1	0.35	ABSENCE	ABSENCE	< 1
06/17/2020 12:38	S20-3881	Water Pump, Main Road, Phase 2, Terra Fortuna	7.30 / 29.5	0.10	ABSENCE	ABSENCE	< 1
06/17/2020 12:49	S20-3882	Block 11 Lot 16, Terra Fortuna	7.13 / 30.1	0.05	ABSENCE	ABSENCE	< 1
06/17/2020 13:07	S20-3879	9999 W, Villa Las Casas	7.21 / 30.7	0.30	ABSENCE	ABSENCE	< 1
06/17/2020 13:15	S20-3880	Block 1 Lot 17, Villa Las Casas	7.18 / 29.7	0.27	ABSENCE	ABSENCE	< 1
<b>BRGY. POOC</b>							
06/15/2020 12:17	S20-3780	Water Pump, Villa Mercedes	7.83 / 31.4	1.36	ABSENCE	ABSENCE	-

NOT VALID WITHOUT QR CODE



REVIEWED BY:

JETHRO D. ESCOBIN  
Microbiology Unit Manager

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT  
Laboratory Services Manager  
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis.

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna  
CONTACT NO.: (049) 543-1916  
WEBSITE: [www.lagunawater.com.ph](http://www.lagunawater.com.ph)

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature <sup>A</sup> ( - / °C)	RESIDUAL CHLORINE <sup>B</sup> (mg/L)	COLIFORM <sup>C</sup>		HPC <sup>D</sup> (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
06/15/2020 12:26	S20-3781	Block 2 Lot 1, Villa Mercedes	7.86 / 31.9	1.28	ABSENCE	ABSENCE	-
06/15/2020 13:09	S20-3784	Block 52 Lot 25, Phase 1, Southville	8.15 / 32.0	0.25	ABSENCE	ABSENCE	-
06/15/2020 12:42	S20-3785	Water Pump, Phase 8 & 9, Southville	8.16 / 30.7	1.36	ABSENCE	ABSENCE	-
06/15/2020 12:49	S20-3786	Block 2 Lot 16, Phase 9, Southville	8.02 / 32.6	0.48	ABSENCE	ABSENCE	-
06/15/2020 13:34	S20-3787	Water Pump, Phase 5, Southville	8.12 / 30.8	0.55	ABSENCE	ABSENCE	-
<b>BRGY. PULONG STA. CRUZ</b>							
06/17/2020 10:27	S20-3872	Block 6 Lot 8, Buklod Diwa	7.18 / 30.5	0.47	ABSENCE	ABSENCE	< 1
06/17/2020 10:59	S20-3883	Drinking Fountain 1, Pulong Sta. Cruz Elementary School	7.18 / 30.5	0.50	ABSENCE	ABSENCE	< 1
06/17/2020 11:07	S20-3884	Drinking Fountain 2, Pulong Sta. Cruz Elementary School	7.16 / 30.6	0.42	ABSENCE	ABSENCE	< 1
<b>BRGY. SANTO DOMINGO</b>							
06/23/2020 13:30	S20-4020	Clubhouse Santa Rosa Estates II	7.15 / 29.6	0.37	ABSENCE	ABSENCE	< 1

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: HPC – Heterotrophic Plate Count; CFU – Colony Forming Units; MDL – Method Detection Limit; LOQ – Limit of Quantification; NA – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.


METHODS: A – Electrometric; B – Colorimetric ; C- Enzyme Substrate; D – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23<sup>rd</sup> Edition


NOT VALID WITHOUT QR CODE



REVIEWED BY:

  
JETHRO D. ESCOBIN  
Microbiology Unit Manager

CERTIFIED CORRECT BY:

  
ANNA KARLA S. GUTIERREZ, RMT  
Laboratory Services Manager  
License No(s). (PRC 0050968)