

DOH Accredited Testing Laboratory (04A-001-1820-LW-2); DENR Environmental Laboratory Recognition (ELR Code 04-30); PNRI (RML No. Y04.04132.17) PRC Certificate of Authority to Operate No. 111 PNP (License No. PDD03-230616-04201)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION (LAGUNA WATER)

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : SANTA ROSA CITY HEALTH OFFICE I (CHO-1)

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 27

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 09/01/2020-09/11/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER						
			pH/ Temperature ^A (-/°C)	RESIDUAL CHLORINE ^B (mg/L) MDL: 0.06	COLIFORMC				
					TOTAL (Coliforms/	FECAL/ E. coli (Coliforms/ 100 mL)	HPC ^D (CFU/mL)		
			MDL: NA		100mL)				
BRGY, BIÑAN			LOQ: NA	LOQ: 0.20					
09/01/2020 12:40	S20-5569	Laguna Wellfield 1	8.74 / 27.5	0.12	ABSENCE	ABSENCE	<1		
BRGY. CAINGIN									
09/09/2020 13:04	S20-5913	Water Pump, Block 57, Phase 1, Southville	7.63 / 31.2	0.34	ABSENCE	ABSENCE	<1		
09/09/2020 13:47	S20-5914	Block 25 Lot 7, Phase 3, Southville	7.52 / 34.0	0.34	ABSENCE	ABSENCE	2		
09/09/2020 13:10	S20-5915	Southville Caingin National High School	7.59 / 31.8	0.24	ABSENCE	ABSENCE	<1		
09/09/2020 13:22	S20-5917	Water Pump, Phase 8 & 9, Southville	7.16 / 30.5	0.14	ABSENCE	ABSENCE	1		
09/09/2020 10:29	S20-5918	Block 16 Lot 2, Phase 9, Southville	7.21 / 31.2	0.08	ABSENCE	ABSENCE	<1		
09/09/2020 13:56	S20-5919	Water Pump, Phase 5, Southville	7.45 / 30.7	0.49	ABSENCE	ABSENCE	< 1		
BRGY. KANLURAN							•		
09/09/2020 12:20	520-5910	Gate Entrance, Alfonso Homes I	7.15 / 31.4	0.39	ABSENCE	ABSENCE	<1		
09/09/2020 12:11	520-5908	#621 Rizal Boulevard	7.11 / 30.8	0.34	ABSENCE	ABSENCE	<1		
BRGY. MALUSAK									
09/09/2020 11:59	S20-5909	Santa Rosa City Hall	7.03 / 33.5	0.27	ABSENCE	ABSENCE	23		
09/09/2020 12:04	S20-5916	Drinking Fountain 1, Central Elementary School	7.09 / 31.9	0.32	ABSENCE	ABSENCE	<1		
BRGY. MARKET AREA	A								
09/09/2020 11:42	S20-5907	Source, Market Area	7.09 / 30.2	0.36	ABSENCE	ABSENCE	<1		
BRGY. SINALHAN									
09/09/2020 11:17	S20-5906	Block 8 Lot 16, Bayshore III	7.14 / 30.7	0.36	ABSENCE	ABSENCE	<1		

NOT VALID WITHOUT QR CODE

REVIEWED BY:

CERTIFIED CORRECT BY:

JETHROD. ESCOBIN Microbiology Unit Manager ANNA KARLA S. GUTIERREZ. RMT Laboratory Services Manager License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAA/Water Corporation. This report is certified to have passed the Laguna AAA/Water Corporation Quality Control procedures for reporting results of analysis



DOH Accredited Testing Laboratory (04A-001-1820-LW-2); DENR Environmental Laboratory Recognition (ELR Code 04-30); PNRI (RML No. Y04.04132.17) PRC Certificate of Authority to Operate No. 111 PNP (License No. PDD03-230616-04201)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER					
			pH/ Temperature ^A (-/°C)	ature ^A CHLORINE ^B (mg/L) : NA MDL: 0.06	COLIFORMC			
					TOTAL (Coliforms/ 100mL)	FECAL/ E. coli (Coliforms/ 100 mL)	HPC ^D (CFU/mL)	
			MDL: NA LOQ: NA					
09/09/2020 10:56	S20-5905	Amoranto Compound, Phase 2, Sinalhan	7.22 / 30.4	0.37	ABSENCE	ABSENCE	<1	
BRGY. TAGAPO								
09/07/2020 16:36	S20-5727	#60 31 JP Rizal Boulevard	7.26 / 28.2	0.64	ABSENCE	ABSENCE	< 1	
09/07/2020 15:57	S20-5729	Block 1 Lot 18, Fairfield of Margana Subdivision	7.36 / 29.0	0.71	ABSENCE	ABSENCE	<1	
09/07/2020 15:31	S20-5737	Water Pump, Rosewood Homes I	7.30 / 28.2	0.87	ABSENCE	ABSENCE	< 1	
09/07/2020 13:36	S20-5738	Block 3 Lot 31, Rosewood Homes I	7.31 / 30.1	0.32	ABSENCE	ABSENCE	<1	
09/07/2020 16:00	\$20-5739	Block 4 Lot 1, Rosewood Homes II	7.34 / 29.4	0.38	ABSENCE	ABSENCE	<1	
09/07/2020 13:46	S20-5728	Pump House, Buena Rosa 1 Subdivision	7.20 / 28.5	0.39	ABSENCE	ABSENCE	<1	
09/07/2020 15:13	S20-5730	Block 1 Lot 64, Buena Rosa 10 Subdivision	7.36 / 28.7	0.67	ABSENCE	ABSENCE	<1	
09/07/2020 14:13	S20-5731	Cistern Tank, SM Sta. Rosa	7.24 / 33.8	0.24	ABSENCE	ABSENCE	<1	
09/07/2020 14:23	S20-5732	Admin Pantry, SM Sta. Rosa	7.31 / 28.5	0.62	ABSENCE	ABSENCE	<1	
09/09/2020 15:38	S20-5920	Cistern Tank, Robinson's Mall	8.01 / 28.9	0.04	ABSENCE	ABSENCE	41	
09/07/2020 14:58	S20-5734	Sizzler's, Robinson's Mall	7.53 / 27.5	0.03	ABSENCE	ABSENCE	24	
09/03/2020 08:10	S20-5653	Water Pump, Metrogate Heritage Subd.	7.30 / 29.5	0.57	ABSENCE	ABSENCE	<1	
09/03/2020 08:27	\$20-5654	Clubhouse, Metrogate Heritage Subd.	7.24 / 29.8	0.50	ABSENCE	ABSENCE	<1	

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: HPC – Heterotrophic Plate Count; CFU – Colony Forming Units; MDL – Method Detection Limit; LOQ – Limit of Quantification; NA – Not Applicable

 $\label{eq:decomposition} \textbf{DEVIATIONS:} \ \ \text{No deviation noted on sample collection and submission.}$

METHODS: \underline{A} – Electrometric; \underline{B} – Colorimetric; \underline{C} - Enzyme Substrate; \underline{D} – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR CODE

REVIEWED BY:

CERTIFIED CORRECT BY:

JETHRO DESCOBNI Microbiology Unit Manager ANNA KARLA S. GOTIERREZ, RMT Laboratory Services Manager License No(s). (RRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAAWater Corporation. This report is certified to have passed the Laguna AAAWater Corporation Quality Control procedures for reporting results of analysis



DOH Accredited Testing Laboratory (04A-001-1820-LW-2); DENR Environmental Laboratory Recognition (ELR Code 04-30); PNRI (RML No. Y04.04132.17) PRC Certificate of Authority to Operate No. 111 PNP (License No. PDD03-230616-04201)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916 WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME: LAGUNA AAAWATER CORPORATION

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : SANTA ROSA CITY HEALTH OFFICE II (CHO-2)

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 47

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 09/01/2020-09/26/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER						
			pH/ Temperature ^A (- / °C) MDL: NA LOQ: NA	RESIDUAL CHLORINE ^B (mg/L) MDL: 0.06 LOQ: 0.20	COLIFORMC				
					TOTAL (Coliforms/ 100mL)	FECAL/ E. coli (Coliforms/ 100 mL)	HPC ^D (CFU/ml		
BRGY. BIÑAN				20 4. 0.20					
09/01/2020 12:40	S20-5569	Laguna Wellfield 1	8.74 / 27.5	0.12	ABSENCE	ABSENCE	<1		
BRGY. BALIBAGO									
09/07/2020 16:36	S20-5726	#1354 Facundo Compound	7.31 / 29.1	0.68	ABSENCE	ABSENCE	1		
09/08/2020 14:50	S20-5808	Clubhouse, South Hampton	6.97 / 29.5	0.35	ABSENCE	ABSENCE	<1		
09/03/2020 15:16	S20-5651	Block 5 Lot 25, JB Village	7.40 / 30.6	0.30	ABSENCE	ABSENCE	<1		
09/21/2020 15:33	S20-6222	Cistern Tank, Waltermart Santa Rosa	7.86 / 31.8	0.16	ABSENCE	ABSENCE	<1		
09/21/2020 15:40	S20-6223	2 nd Floor Faucet, Waltermart Santa Rosa	7.74 / 33.0	0.14	ABSENCE	ABSENCE	14		
BRGY. DILA									
09/03/2020 10:58	S20-5639	Water Pump, Phase 3E, Mabuhay Homes 2000	7.30 / 30.1	0.20	ABSENCE	ABSENCE	<1		
09/03/2020 11:16	S20-5640	Block 2 Lot 10, Mabuhay Homes 2000	7.27 / 29.7	0.14	ABSENCE	ABSENCE	<1		
09/03/2020 11:40	\$20-5641	Water Pump, Block 12, Phase 2E, Mabuhay Homes 2000	7.24 / 29.4	0.20	ABSENCE	ABSENCE	<1		
09/03/2020 12:07	S20-5642	Block 13 Lot 5, Phase 2E, Mabuhay Homes 2000	7.37 / 30.6	0.17	ABSENCE	ABSENCE	<1		
09/03/2020 12:34	S20-5643	Drinking Fountain, Dila Elementary School	7.27 / 30.5	0.35	ABSENCE	ABSENCE	1		
09/08/2020 14:38	S20-5818	Clubhouse, Villa Esmeralda	7.06 / 30.6	0.39	ABSENCE	ABSENCE	<1		
BRGY. DITA									
09/03/2020 13:18	S20-5644	Block 24 Lot 2, New Santa Rosa Homes	7.22 / 29.5	0.30	ABSENCE	ABSENCE	8		
09/03/2020 13:40	S20-5645	Block 19 Lot 11, New Santa Rosa Homes	7.29 / 28.7	0.22	ABSENCE	ABSENCE	<1		
09/08/2020 14:25	S20-5809	Block 11 lot 52, San Lorenzo Royale	7.25 / 30.5	0.38	ABSENCE	ABSENCE	<1		
09/03/2020 14:20	S20-5646	Water Tank, SolCar Ville Subdivision	7.37 / 30.3	0.40	ABSENCE	ABSENCE	<1		
09/03/2020 14:48	S20-5647	Block 3 Lot 7, SolCar Ville Subdivision	7.29 / 29.8	0.32	ABSENCE	ABSENCE	27		

NOT VALID WITHOUT QR CODE

REVIEWED BY:

CERTIFIED CORRECT BY:

JETHRO D. ESCOMMICrobiology Unit Manager

ANNA KARLA S. GUTTERREZ, RMT Laboratory Services Manager License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAAWater Corporation. This report is certified to have passed the Laguna AAAWater Corporation Quality Control procedures for reporting results of analysis.



DOH Accredited Testing Laboratory (04A-001-1820-LW-2); DENR Environmental Laboratory Recognition (ELR Code 04-30); PNRI (RML No. Y04.04132.17) PRC Certificate of Authority to Operate No. 111 PNP (License No. PDD03-230616-04201)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

			PARAMETER						
DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	pH/ RESIDUAL COLIFORM ^C						
			Temperature ^A (- / °C) MDL: NA LOQ: NA	CHLORINE ^B (mg/L) MDL: 0.06 LOQ: 0.20	TOTAL (Coliforms/ 100mL)	FECAL/ E. coli (Coliforms/ 100 mL)	HPC ^D (CFU/ml		
09/03/2020 10:07	520-5648	#1780 National Road	7.21 / 29.4	0.25	ABSENCE	ABSENCE	<1		
9/03/2020 10:30	S20-5654	R & B Ice Plant, Inc.	7.30 / 29.4	0.30	ABSENCE	ABSENCE	<1		
BRGY. DON JOSE		V							
09/10/2020 12:06	S20-5929	Science High School, Phase 1, Laguna Bel- Air	7.27 / 27.8	0.39	ABSENCE	ABSENCE	-		
09/10/2020 11:02	S20-5931	Church, Block 108, Phase 5, Laguna Bel- Air	7.22 / 33.2	0.29	ABSENCE	ABSENCE	-		
09/10/2020 12:36	S20-5930	Clubhouse, Laguna Bel-Air I	7.34 / 28.7	0.45	ABSENCE	ABSENCE	-		
09/10/2020 11:56	S20-5935	Block 47 Lot 12 Laguna Bel-Air IV	7.29 / 31.7	0.37	ABSENCE	ABSENCE	-		
09/10/2020 13:56	S20-5923	8001, Pump 1, Acacia St., Santa Rosa Village I	7.29 / 26.9	0.50	ABSENCE	ABSENCE	-		
09/10/2020 14:01	S20-5924	Clubhouse. Phase 4B, Santa Rosa Village I	7.30 / 29.0	0.46	ABSENCE	ABSENCE	-		
09/10/2020 14:11	520-5925	Clubhouse, Santa Rosa Village II	7.21 / 28.8	0.19	ABSENCE	ABSENCE			
09/10/2020 13:37	520-5926	Pump 9 & 10, Santa Rosa Estates I	7.51 / 27.4	0.14	ABSENCE	ABSENCE			
09/10/2020 13:41	S20-5927	Clubhouse, Santa Rosa Estates I	7.32 / 28.7	0.15	ABSENCE	ABSENCE			
09/25/2020 12:00	S20-6259	Drinking Fountain, Don Jose National High School	8.02 / 28.3	0.47	ABSENCE	ABSENCE	-		
BRGY. MACABLING						40-			
09/07/2020 13:31	S20-5740	Water Pump, Buena Rosa 9 Subdivision	7.13 / 28.9	0.38	ABSENCE	ABSENCE	1		
09/07/2020 13:37	S20-5741	Block 4 Lot 44, Phase 1, Buena Rosa 9 Subdivision	7.16 / 29.2	0.34	ABSENCE	ABSENCE	1		
09/07/2020 13:11	S20-5735	Water Pump, Corinthian Subdivision	7.03 / 28.8	0.67	ABSENCE	ABSENCE	140		
09/07/2020 13:19	S20-5736	Block 11 Lot 19, Corinthian Subdivision	7.12 / 31.5	0.61	ABSENCE	ABSENCE	1		
BRGY. MALITLIT									
09/03/2020 09:47	S20-5649	Clubhouse, Casan Residencia Subdivision	7.16 / 29.7	0.12	ABSENCE	ABSENCE	<1		
09/08/2020 13:56	S20-5810	Block 3 Lot 1, Phase 1A Annex, San Lorenzo Subd.	7.10 / 29.1	0.86	ABSENCE	ABSENCE	<1		
09/08/2020 13:52	S20-5811	Block 5 Lot 25, Phase 1A Annex, San Lorenzo Subd.	7.19 / 29.3	0.86	ABSENCE	ABSENCE	1		
09/08/2020 14:08	S20-5814	Water Pump, Main Road, Phase 2, Terra Fortuna	7.54 / 29.4	0.59	ABSENCE	ABSENCE	< 1		
09/08/2020 14:13	S20-5815	Block 11 Lot 16, Terra Fortuna	7.56 / 28.9	0.59	ABSENCE	ABSENCE	< 1		
09/08/2020 13:36	S20-5812	9999 W, Villa Las Casas	6.76 / 29.3	0.63	ABSENCE	ABSENCE	< 1		
09/08/2020 13:43	520-5813	Block 1 Lot 17, Villa Las Casas	6.86 / 30.7	0.83	ABSENCE	ABSENCE	<1		
09/03/2020 09:10	S20-5650	Drinking Fountain, Malitlit Elementary School	7.33 / 29.5	0.17	ABSENCE	ABSENCE	11		
BRGY. POOC									

NOT VALID WITHOUT QR CODE

REVIEWED BY:

CERTIFIED CORRECT BY:

JETHRO D. ESCOBIN Microbiology Unit Manager ANNA KARLA 8. GUTTERREZ, RMT Laboratory Services Manager License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAAWater Corporation. This report is certified to have passed the Laguna AAAWater Corporation Quality Control procedures for reporting results of analysis.



DOH Accredited Testing Laboratory (04A-001-1820-LW-2); DENR Environmental Laboratory Recognition (ELR Code 04-30); PNRI (RML No. Y04.04132.17) PRC Certificate of Authority to Operate No. 111 PNP (License No. PDD03-230616-04201)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916 WEBSITE: www.lagunawater.com/ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER						
			pH/	RESIDUAL	COLIFORMC				
			Temperature ^A (- / °C) MDL: NA LOQ: NA	(mg/L) MDL: 0.06 LOQ: 0.20	TOTAL (Coliforms/ 100mL)	FECAL/ E. coli (Coliforms/ 100 mL)	HPC ^D (CFU/mL)		
09/09/2020 12:38	520-5911	Water Pump, Villa Mercedez	7.38 / 30.9	0.24	ABSENCE	ABSENCE	<1		
09/09/2020 12:47	S20-5912	Block 2 Lot 1, Villa Mercedez	7.43 / 20.8	0.17	ABSENCE	ABSENCE	<1		
BRGY. PULONG STA.	CRUZ								
09/08/2020 15:13	\$20-5807	Block 6 Lot 8, Buklod Diwa	7.18 / 29.4	0.42	ABSENCE	ABSENCE	1		
09/08/2020 13:12	S20-5816	Drinking Fountain 1, Pulong Sta. Cruz Elementary School	7.01 / 29.8	0.43	ABSENCE	ABSENCE	<1		
09/08/2020 13:17	S20-5817	Wash Area, Pulong Sta. Cruz Elementary School	7.08 / 28.8	0.39	ABSENCE	ABSENCE	<1		
BRGY. SANTO DOMI	NGO								
09/10/2020 13:21	S20-5928	Clubhouse Santa Rosa Estates II	7.29 / 0.21	0.21	ABSENCE	ABSENCE			

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: HPC - Heterotrophic Plate Count; CFU - Colony Forming Units; MDL - Method Detection Limit; LOQ - Limit of Quantification; NA - Not Applicable **DEVIATIONS:** No deviation noted on sample collection and submission.

METHODS: A - Electrometric; B - Colorimetric; C- Enzyme Substrate; D - Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR CODE

REVIEWED BY:

JETHRO D. ESCOB Microbiology Unit Manager **CERTIFIED CORRECT BY:**

Laboratory Services Manager

License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAAWater Corporation. This report is certified to have passed the Laguna AAAWater Corporation Quality Control procedures for reporting results of analysis.