

DOH Accredited Testing Laboratory (04A-001-1820-LW-2); PNRI (RML No. Y04.04132.17); and PNP (License No. PDD03-230616-04201)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

Test Report ID : TR-19-2882

Date Prepared

: 10/07/2019

Sample Code

: S19-5231

Name of Company / Customer

: Laguna Water Corporation

Address

: G/F, One Evotech Building, Nuvali, Brgy. Sto. Domingo, Sta. Rosa City, Laguna

Date/Time Collected

: 09/17/2019 17:01

Date/Time Submitted : 09/17/2019 21:10

Collected By

: Ohwen L. Catindig

Submitted By

: Ohwen L. Catindig

Condition of Sample Upon Receipt

: 100 mL water sample in clear, polystyrene, sterile container with 3% sodium

thiosulfate

Sample Source Characteristics

: Source - Treated Water (w/ Chlorination)

References

: Standard Methods for the Examination of Water and Wastewater, 23rd Edition : DOH AO 2017-0010 "Philippine National Standards for Drinking Water of 2017"

RESULTS OF LABORATORY ANALYSIS

SAMPLE LOCATION : SOURCE, AFTER DMI-65 FILTRATION, LAGUNA SPORTS COMPLEX, BUBUKAL, STA. CRUZ, LAGUNA

PARAMETER(S)	UNIT(S)	RESULT(S)	PNSDW LIMIT(/S)	METHOD(S)	ANALYZED	
					DATE	BY
Total Coliform	Coliforms/100 mL	ABSENCE	ABSENCE	9223B. Enzyme Substrate Test (Colilert-18®)	9/17/2019	JDE
Thermotolerant Coliform / Escherichia coli	Coliforms/100 mL	ABSENCE	ABSENCE	9223B. Enzyme Substrate Test (Colilert-18®)	9/17/2019	JDE
Heterotrophic Plate Count	CFU/mL	14	500 (max.)	9215B. Pour Plate Method	9/17/2019	JDE

Remarks: Samples analyzed as submitted. No deviations noted on sample collection and submission.

CERTIFIED CORRECT BY:

ANNA KARLA S. OUTIERREZ, RMT Microbiologist, Head

PRC License No. 0060968

NOTED BY:

CYRIL A. ERICA, RMT, MLS(ASCP)^{CM}
Laboratory Services Manager

License No(s). (PRC 0054161/ASCP 10981)

Test Report QC Checked By:

Date of Test Report QC Check:

10/1/10/1



DOH Accredited Testing Laboratory (04A-001-1820-LW-2);
PNRI (RML No. Y04.04132.17); and PNP (License No. PDD03-230616-04201)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

Date Prepared

: 10/07/2019

Test Report ID
Sample Code

: S19-5232

: TR-19-2883

Name of Company / Customer

: Laguna Water Corporation

Address

♂G/F, One Evotech Building, Nuvali, Brgy. Sto. Domingo, Sta. Rosa City, Laguna

Date/Time Collected

: 09/17/2019 16:54

Date/Time Submitted : 09/17/2019 21:10

Collected By

: Ohwen L. Catindig

Submitted By

: Ohwen L. Catindig

Condition of Sample Upon Receipt

: 100 mL water sample in clear, polystyrene, sterile container with 3% sodium

thiosulfate

Sample Source Characteristics

: Distribution – Network Sampling Point

References

: Standard Methods for the Examination of Water and Wastewater, 23rd Edition : DOH AO 2017-0010 "Philippine National Standards for Drinking Water of 2017"

RESULTS OF LABORATORY ANALYSIS

SAMPLE LOCATION : GRANDSTAND, LAGUNA SPORTS COMPLEX, BUBUKAL, STA. CRUZ,

LAGUNA

PARAMETER(S)	UNIT(S)	RESULT(S)	PNSDW LIMIT(/S)	METHOD(S)	ANALYZED	
					DATE	BY
Total Coliform	Coliforms/100 mL	ABSENCE	ABSENCE	9223B. Enzyme Substrate Test (Colilert-18®)	9/17/2019	JDE
Thermotolerant Coliform / Escherichia coli	Coliforms/100 mL	ABSENCE	ABSENCE	9223B. Enzyme Substrate Test (Colilert-18®)	9/17/2019	JDE
Heterotrophic Plate Count	CFU/mL	<1	500 (max.)	9215B. Pour Plate Method	9/17/2019	JDE

Remarks: Samples analyzed as submitted. No deviations noted on sample collection and submission.

CERTIFIED CORRECT BY:

ANNA KARLA SI SUTIERREZ, RMT

Microbio ogist, Head

PRC License No. 0060968

NOTED BY:

CYRIL A. ERICA, RMT MLS(ASCP)CM

Laboratory services Manager

License No(s). (PRC 0054161/ASCP 10981)

Test Report QC Checked By:

Date of Test Report QC Check:

10/7/2019



DOH Accredited Testing Laboratory (04A-001-1820-LW-2); PNRI (RML No. Y04.04132.17); and PNP (License No. PDD03-230616-04201)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916 WEBSITE: www.lagunawater.com.ph

Test Report ID

: TR-19-2884

Date Prepared

: 10/07/2019

Sample Code

: S19-5233

Name of Company / Customer

: Laguna Water Corporation

Address

G/F, One Evotech Building, Nuvali, Brgy. Sto. Domingo, Sta. Rosa City, Laguna

Date/Time Collected

: 09/17/2019 17:25

Date/Time Submitted : 09/17/2019 21:10

Collected By

Ohwen L. Catindig

Submitted By

: Ohwen L. Catindig

Condition of Sample Upon Receipt

: 100 mL water sample in clear, polystyrene, sterile container with 3% sodium

thiosulfate

Sample Source Characteristics

: Source - Treated Water (w/ Chlorination)

References

: Standard Methods for the Examination of Water and Wastewater, 23rd Edition : DOH AO 2017-0010 "Philippine National Standards for Drinking Water of 2017"

RESULTS OF LABORATORY ANALYSIS

SAMPLE LOCATION: WATER PUMP, CAPITOL COMPOUND, P. GUEVARRA AVE., LAGUNA PROVINCIAL CAPITOL, STA. CRUZ, LAGUNA

PARAMETER(S)	UNIT(S)	RESULT(S)	PNSDW LIMIT(/S)	METHOD(S)	ANALYZED	
					DATE	BY
Total Coliform	Coliforms/100 mL	ABSENCE	ABSENCE	9223B. Enzyme Substrate Test (Colilert-18®)	9/17/2019	JDE
Thermotolerant Coliform / Escherichia coli	Coliforms/100 mL	ABSENCE	ABSENCE	9223B. Enzyme Substrate Test (Colilert-18®)	9/17/2019	JDE
Heterotrophic Plate Count	CFU/mL	< 1	500 (max.)	9215B. Pour Plate Method	9/17/2019	JDE

Remarks: Samples analyzed as submitted. No deviations noted on sample collection and submission.

CERTIFIED CORRECT BY:

ANNA KARLAS QUTIERREZ, RMT

Microbiologist, Head

PRC License No. 0060968

NOTED BY:

CYRIL A. ERICA, RIMT, MLS(ASCP)CM

Laboratory Services Manager

License No(s). (PRC 0054161/ASCP 10981)

Test Report QC Checked By:

Date of Test Report QC Check:

10/7/2019



DOH Accredited Testing Laboratory (04A-001-1820-LW-2); PNRI (RML No. Y04.04132.17); and PNP (License No. PDD03-230616-04201)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

Test Report ID : TR-19-2885 Date Prepared : 10/07/2019

Sample Code : \$19-5234

Name of Company / Customer : Laguna Water Corporation

Address : G/F, One Evotech Building, Nuvali, Brgy. Sto. Domingo, Sta. Rosa City, Laguna

Date/Time Collected : 09/17/2019 18:03 Date/Time Submitted : 09/17/2019 21:10

Collected By : Ohwen L. Catindig Submitted By : Ohwen L. Catindig

Condition of Sample Upon Receipt : 100 mL water sample in clear, polystyrene, sterile container with 3% sodium

thiosulfate

Sample Source Characteristics : Distribution – Network Sampling Point

References : Standard Methods for the Examination of Water and Wastewater, 23rd Edition : DOH AO 2017-0010 "Philippine National Standards for Drinking Water of 2017"

RESULTS OF LABORATORY ANALYSIS

SAMPLE LOCATION : OLD CAPITOL BUILDING, CAPITOL COMPOUND, P. GUEVARRA AVE., LAGUNA PROVINCIAL CAPITOL, STA. CRUZ, LAGUNA

PARAMETER(S)	UNIT(S)	RESULT(S)	PNSDW LIMIT(/S)	METHOD(S)	ANALYZED	
					DATE	BY
Total Coliform	Coliforms/100 mL	ABSENCE	ABSENCE	9223B. Enzyme Substrate Test (Colilert-18®)	9/17/2019	JDE
Thermotolerant Coliform / Escherichia coli	Coliforms/100 mL	ABSENCE	ABSENCE	9223B. Enzyme Substrate Test (Colilert-18®)	9/17/2019	JDE
Heterotrophic Plate Count	CFU/mL	11	500 (max.)	9215B. Pour Plate Method	9/17/2019	JDE

Remarks: Samples analyzed as submitted. No deviations noted on sample collection and submission.

CERTIFIED CORRECT BY:

ANNA KARLAS. GUTIERREZ, RMT

Microbio ogist, Head

PRC License No. 0060968

NOTED BY:

CYRIL A. ERICA, RMT, MLS(ASCP)CM

Laboratory Services Manager

License No(s). (PRC 0054161/ASCP 10981)

Test Report QC Checked By:

Date of Test Report QC Check:

10/7/10/9



DOH Accredited Testing Laboratory (04A-001-1820-LW-2); PNRI (RML No. Y04.04132.17); and PNP (License No. PDD03-230616-04201)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

Test Report ID

: TR-19-2886

Date Prepared

: 10/07/2019

Sample Code

: S19-5235

Name of Company / Customer

: Laguna Water Corporation

Address

: G/F, One Evotech Building, Nuvali, Brgy. Sto. Domingo, Sta. Rosa City, Laguna

Date/Time Collected

: 09/17/2019 17:35

Date/Time Submitted : 09/17/2019 21:10

Collected By

: Ohwen L. Catindig

Submitted By

Ohwen L. Catindig

Condition of Sample Upon Receipt

: 100 mL water sample in clear, polystyrene, sterile container with 3% sodium

thiosulfate

Sample Source Characteristics

: Distribution – Network Sampling Point

References

: Standard Methods for the Examination of Water and Wastewater, 23rd Edition : DOH AO 2017-0010 "Philippine National Standards for Drinking Water of 2017"

RESULTS OF LABORATORY ANALYSIS

SAMPLE LOCATION : CISTERN TANK, LAGUNA MEDICAL CENTER, STA. CRUZ, LAGUNA

PARAMETER(S)	UNIT(S)	RESULT(S)	PNSDW LIMIT(/S)	METHOD(S)	ANALYZED	
	Olvii (3)				DATE	BY
Total Coliform	Coliforms/100 mL	ABSENCE	ABSENCE	9223B. Enzyme Substrate Test (Colilert-18®)	9/17/2019	JDE
Thermotolerant Coliform / Escherichia coli	Coliforms/100 mL	ABSENCE	ABSENCE	9223B. Enzyme Substrate Test (Colilert-18®)	9/17/2019	JDE
Heterotrophic Plate Count	CFU/mL	27	500 (max.)	9215B. Pour Plate Method	9/17/2019	JDE

Remarks: Samples analyzed as submitted. No deviations noted on sample collection and submission.

CERTIFIED CORRECT BY:

ANNA KARLA S. SUTHERREZ, RIMT

Microbiologist, Head PRC License No. 006,0968 **NOTED BY:**

CYRIL A. ERICA RMT, MLS(ASCP)^{CM}
Laboratory Services Manager

License No(s). (PRC 0054161/ASCP 10981)

Test Report QC Checked By:

Date of Test Report QC Check:

rairlal



DOH Accredited Testing Laboratory (04A-001-1820-LW-2); PNRI (RML No. Y04.04132.17); and PNP (License No. PDD03-230616-04201)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

Test Report ID

: TR-19-2887

Date Prepared

: 10/07/2019

Sample Code

: \$19-5236

Name of Company / Customer

: Laguna Water Corporation

Address

G/F, One Evotech Building, Nuvali, Brgy. Sto. Domingo, Sta. Rosa City, Laguna

Date/Time Collected

: 09/17/2019 17:30

Date/Time Submitted : 09/17/2019 21:10

Collected By

: Ohwen L. Catindig

Submitted By

Ohwen L. Catindig

Condition of Sample Upon Receipt

: 100 mL water sample in clear, polystyrene, sterile container with 3% sodium

thiosulfate

Sample Source Characteristics

: Distribution – Network Sampling Point

References

: Standard Methods for the Examination of Water and Wastewater, 23rd Edition : DOH AO 2017-0010 "Philippine National Standards for Drinking Water of 2017"

RESULTS OF LABORATORY ANALYSIS

SAMPLE LOCATION : KITCHEN FAUCET, LAGUNA MEDICAL CENTER, STA. CRUZ, LAGUNA

PARAMETER(S)	UNIT(S)	RESULT(S)	PNSDW LIMIT(/S)	METHOD(S)	ANALYZED	
					DATE	BY
Total Coliform	Coliforms/100 mL	ABSENCE	ABSENCE	9223B. Enzyme Substrate Test (Colilert-18®)	9/17/2019	JDE
Thermotolerant Coliform / Escherichia coli	Coliforms/100 mL	ABSENCE	ABSENCE	9223B. Enzyme Substrate Test (Colilert-18®)	9/17/2019	JDE
Heterotrophic Plate Count	CFU/mL	< 1	500 (max.)	9215B. Pour Plate Method	9/17/2019	JDE

Remarks: Samples analyzed as submitted. No deviations noted on sample collection and submission.

CERTIFIED CORRECT BY:

ANNA KARLA J. SUTIERREZ, RMT

Microbiologist, Head PRC License No. 0060968 NOTED BY:

CYRIL A. ERICA, RMT MLS(ASCP)^{CM}
Laboratory Services Manager

License No(s). (PRC 0054161/ASCP 10981)

Test Report QC Checked By:

Date of Test Report QC Check:

10/7/2019