

**ADDRESS:** 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna  
**CONTACT NO.:** (049) 543-1916  
**WEBSITE:** [www.lagunawater.com.ph](http://www.lagunawater.com.ph)

**CUSTOMER NAME :** LAGUNA AAAWATER CORPORATION (LAGUNA WATER)

**ADDRESS :** G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

**ATTENTION :** SANTA ROSA CITY HEALTH OFFICE I (CHO-1)

### SUMMARY OF LABORATORY ANALYSIS

**NO. OF SAMPLES :** 26

**TOTAL PARAMETERS TESTED :** 5

**ANALYSIS DATE(S) :** 10/01/2020-10/10/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature <sup>A</sup> (- / °C)	RESIDUAL CHLORINE <sup>B</sup> (mg/L)	COLIFORM <sup>C</sup>		HPC <sup>D</sup> (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
<b>BRGY. BIÑAN</b>							
10/07/2020 12:40	S20-6721	Laguna Wellfield 1	7.49 / 30.4	0.87	ABSENCE	ABSENCE	< 1
<b>BRGY. CAINGIN</b>							
10/01/2020 15:14	S20-6483	Water Pump, Block 57, Phase 1, Southville	7.91 / 30.7	0.22	ABSENCE	ABSENCE	< 1
10/01/2020 16:38	S20-6484	Block 25 Lot 7, Phase 3, Southville	7.81 / 30.4	0.30	ABSENCE	ABSENCE	< 1
10/01/2020 15:20	S20-6485	Southville Integrated Highschool	7.81 / 31.1	0.20	ABSENCE	ABSENCE	6
10/01/2020 16:04	S20-6487	Water Pump, Phase 8 & 9, Southville	7.57 / 30.1	0.69	ABSENCE	ABSENCE	< 1
10/01/2020 16:16	S20-6488	Block 16 Lot 2, Phase 9, Southville	7.54 / 31.2	0.38	ABSENCE	ABSENCE	< 1
10/01/2020 16:27	S20-6489	Water Pump, Phase 5, Southville	7.85 / 30.1	0.33	ABSENCE	ABSENCE	< 1
<b>BRGY. KANLURAN</b>							
10/01/2020 13:38	S20-6480	Gate Entrance, Alfonso Homes I	7.60 / 30.0	0.35	ABSENCE	ABSENCE	< 1
10/01/2020 13:32	S20-6478	#621 Rizal Boulevard	7.54 / 30.4	0.36	ABSENCE	ABSENCE	< 1
<b>BRGY. MALUSAK</b>							
10/01/2020 13:18	S20-6479	Santa Rosa City Hall	7.51 / 31.3	0.36	ABSENCE	ABSENCE	< 1
10/01/2020 13:26	S20-6486	Drinking Fountain 1, Central Elementary School	7.56 / 30.9	0.34	ABSENCE	ABSENCE	< 1

NOT VALID WITHOUT QR CODE



REVIEWED BY:

JETHRO D. ESCOBIN  
Microbiology Unit Manager

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT  
Laboratory Services Manager  
License No(s) (PRC 0060968)

*This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis*

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna  
CONTACT NO.: (049) 543-1916  
WEBSITE: [www.lagunawater.com.ph](http://www.lagunawater.com.ph)

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature <sup>A</sup> (- / °C)	RESIDUAL CHLORINE <sup>B</sup> (mg/L)	COLIFORM <sup>C</sup>		HPC <sup>D</sup> (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
<b>BRGY. SINALHAN</b>							
10/01/2020 12:12	S20-6476	Amoranto Compound, Purok 2, Sinalhan	7.62 / 30.4	0.31	ABSENCE	ABSENCE	< 1
10/01/2020 12:35	S20-6477	Block 8 Lot 16, Bayshore III	7.58 / 31.9	0.27	ABSENCE	ABSENCE	< 1
<b>BRGY. TAGAPO</b>							
10/06/2020 11:32	S20-6571	#60 31 JP Rizal Boulevard	7.84 / 29.2	0.48	ABSENCE	ABSENCE	< 1
10/06/2020 12:25	S20-6573	Block 1 Lot 18, Fairfield of Margana Subdivision	7.92 / 30.2	0.50	ABSENCE	ABSENCE	< 1
10/06/2020 13:04	S20-6581	Water Pump, Rosewood Homes I	8.85 / 29.0	0.68	ABSENCE	ABSENCE	< 1
10/06/2020 13:10	S20-6582	Block 3 Lot 31, Rosewood Homes I	8.23 / 30.7	0.49	ABSENCE	ABSENCE	< 1
10/06/2020 12:36	S20-6583	Block 4 Lot 1, Rosewood Homes II	7.68 / 30.4	0.52	ABSENCE	ABSENCE	< 1
10/06/2020 11:20	S20-6572	Pump House, Buena Rosa 1 Subdivision	7.91 / 27.5	0.11	ABSENCE	ABSENCE	< 1
10/06/2020 11:49	S20-6574	Block 1 Lot 64, Buena Rosa 10 Subdivision	7.66 / 30.0	0.55	ABSENCE	ABSENCE	< 1
10/06/2020 13:56	S20-6575	Cistern Tank, SM Sta. Rosa	8.40 / 31.0	0.52	ABSENCE	ABSENCE	1
10/06/2020 14:02	S20-6576	Admin Pantry, SM Sta. Rosa	8.40 / 28.2	0.65	ABSENCE	ABSENCE	22
10/08/2020 10:22	S20-6745	Cistern Tank, Robinson's Mall	8.17 / 28.7	0.77	ABSENCE	ABSENCE	47
10/06/2020 13:37	S20-6578	Paotsin, Robinson's Mall	8.68 / 27.8	0.06	ABSENCE	ABSENCE	18
10/05/2020 15:16	S20-6564	Water Pump, Metrogate Heritage Subd.	7.47 / 30.6	0.11	ABSENCE	ABSENCE	21
10/06/2020 15:01	S20-6668	Clubhouse, Metrogate Heritage Subd.	7.32 / 30.5	0.97	ABSENCE	ABSENCE	130

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.


METHODS: **A** – Electrometric; **B** – Colorimetric; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23<sup>rd</sup> Edition


NOT VALID WITHOUT QR CODE



REVIEWED BY:

  
JETHRO D. ESCOBIN  
Microbiology Unit Manager

CERTIFIED CORRECT BY:

  
ANNA KARLA S. GUTIERREZ, RMT  
Laboratory Services Manager  
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna  
CONTACT NO.: (049) 543-1916  
WEBSITE: [www.lagunawater.com.ph](http://www.lagunawater.com.ph)

**CUSTOMER NAME : LAGUNA AAAWATER CORPORATION (LAGUNA WATER)**

**ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna**

**ATTENTION : SANTA ROSA CITY HEALTH OFFICE II (CHO-2)**

### SUMMARY OF LABORATORY ANALYSIS

**NO. OF SAMPLES : 46**

**TOTAL PARAMETERS TESTED : 5**

**ANALYSIS DATE(S) : 10/01/2020-10/24/2020**

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature <sup>A</sup> (- / °C)  MDL: NA LOQ: NA	RESIDUAL CHLORINE <sup>B</sup> (mg/L)  MDL: 0.06 LOQ: 0.20	COLIFORM <sup>C</sup>		HPC <sup>D</sup> (CFU/mL)
				TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)		
<b>BRGY. BIÑAN</b>							
10/07/2020 12:40	S20-6721	Laguna Wellfield 1	7.49 / 30.4	0.87	ABSENCE	ABSENCE	< 1
<b>BRGY. BALIBAGO</b>							
10/06/2020 14:55	S20-6570	#1354 Facundo Compound	8.02 / 29.3	0.26	ABSENCE	ABSENCE	< 1
10/05/2020 11:22	S20-6508	Clubhouse, South Hampton	7.83 / 29.2	0.02	ABSENCE	ABSENCE	< 1
10/05/2020 14:57	S20-6563	Block 5 Lot 25, JB Village	7.55 / 29.5	0.28	ABSENCE	ABSENCE	52
10/22/2020 09:47	S20-7141	Cistern Tank, Waltermart Santa Rosa	-	0.04	ABSENCE	ABSENCE	< 1
<b>BRGY. DILA</b>							
10/05/2020 10:17	S20-6551	Water Pump, Phase 3E, Mabuhay Homes 2000	7.44 / 29.7	0.45	ABSENCE	ABSENCE	< 1
10/05/2020 10:40	S20-6552	Block 2 Lot 10, Mabuhay Homes 2000	7.40 / 30.1	0.25	ABSENCE	ABSENCE	9
10/08/2020 13:07	S20-6722	Water Pump, Block 12, Phase 2E, Mabuhay Homes 2000	7.54 / 29.7	0.30	ABSENCE	ABSENCE	45
10/05/2020 11:07	S20-6554	Block 13 Lot 5, Phase 2E, Mabuhay Homes 2000	7.39 / 30.5	0.27	ABSENCE	ABSENCE	27
10/08/2020 12:40	S20-6723	Drinking Fountain, Dila Elementary School	7.44 / 28.9	0.24	ABSENCE	ABSENCE	14
10/05/2020 13:02	S20-6518	Clubhouse, Villa Esmeralda	7.69 / 30.4	0.04	ABSENCE	ABSENCE	1
<b>BRGY. DITA</b>							
10/05/2020 12:10	S20-6556	Block 24 Lot 2, New Santa Rosa Homes	7.44 / 29.3	0.25	ABSENCE	ABSENCE	< 1
10/08/2020 12:16	S20-6724	Block 19 Lot 11, New Santa Rosa Homes	7.41 / 30.1	0.20	ABSENCE	ABSENCE	16
10/08/2020 11:59	S20-6725	Water Tank, SolCar Ville Subdivision	7.37 / 29.6	0.40	ABSENCE	ABSENCE	10
10/06/2020 15:22	S20-6667	Block 3 Lot 7, SolCar Ville Subdivision	7.45 / 30.6	0.22	ABSENCE	ABSENCE	15

NOT VALID WITHOUT QR CODE



REVIEWED BY:

JETHRO D. ESCOBIN  
Microbiology Unit Manager

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ RMT  
Laboratory Services Manager  
License No(s). (PRC 0060968)

*This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis.*

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna  
CONTACT NO.: (049) 543-1916  
WEBSITE: [www.lagunawater.com.ph](http://www.lagunawater.com.ph)

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	pH/ Temperature <sup>A</sup> (- / °C)	RESIDUAL CHLORINE <sup>B</sup> (mg/L)	PARAMETER		HPC <sup>D</sup> (CFU/mL)
					COLIFORM <sup>C</sup>		
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20	TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
10/06/2020 15:48	S20-6666	#1780 National Road	7.41 / 29.6	0.31	ABSENCE	ABSENCE	31
10/05/2020 12:48	S20-6566	R & B Ice Plant, Inc.	7.43 / 29.6	0.30	ABSENCE	ABSENCE	58
10/05/2020 12:48	S20-6509	Block 11 Lot 52, San Lorenzo Royale	7.60 / 30.6	0.05	ABSENCE	ABSENCE	< 1
<b>BRGY. DON JOSE</b>							
10/08/2020 12:47	S20-6752	Science High School, Phase 1, Laguna Bel-Air	7.79 / 26.5	0.83	ABSENCE	ABSENCE	< 1
10/08/2020 14:08	S20-6754	Church, Block 108, Phase 5, Laguna Bel-Air	7.98 / 27.4	0.83	ABSENCE	ABSENCE	250
10/08/2020 12:02	S20-6753	Clubhouse, Phase 1, Laguna Bel-Air I	7.93 / 27.1	0.82	ABSENCE	ABSENCE	< 1
10/08/2020 12:39	S20-6758	Block 47 Lot 12, Laguna Bel-Air IV	7.78 / 27.7	0.81	ABSENCE	ABSENCE	2
10/08/2020 14:08	S20-6746	8001, Pump 1, Acacia St., Santa Rosa Village I	7.89 / 26.0	0.57	ABSENCE	ABSENCE	3
10/08/2020 13:59	S20-6747	Clubhouse, Phase 4B, Santa Rosa Village I	7.94 / 27.9	0.52	ABSENCE	ABSENCE	< 1
10/08/2020 14:21	S20-6748	Clubhouse, Santa Rosa Village II	7.82 / 27.4	0.57	ABSENCE	ABSENCE	1
10/08/2020 13:25	S20-6749	Pump 9 & 10, Santa Rosa Estates I	7.85 / 26.7	0.58	ABSENCE	ABSENCE	< 1
10/08/2020 13:30	S20-6750	Clubhouse, Santa Rosa Estates I	7.72 / 27.3	0.70	ABSENCE	ABSENCE	8
10/12/2020 15:44	S20-6862	Drinking Fountain, Don Jose National High School	7.74 / 28.5	0.93	ABSENCE	ABSENCE	14
<b>BRGY. MACABLING</b>							
10/06/2020 14:24	S20-6584	Water Pump, Buena Rosa 9 Subdivision	8.04 / 28.5	0.27	ABSENCE	ABSENCE	3
10/06/2020 14:37	S20-6585	Block 4 Lot 26, Phase 2, Buena Rosa 9 Subdivision	8.01 / 29.2	0.24	ABSENCE	ABSENCE	< 1
10/06/2020 14:40	S20-6579	Water Pump, Corinthian Subdivision	7.91 / 28.5	0.30	ABSENCE	ABSENCE	290
10/06/2020 14:46	S20-6580	Block 11 Lot 19, Corinthian Subdivision	7.93 / 30.5	0.20	ABSENCE	ABSENCE	< 1
<b>BRGY. MALITLIT</b>							
10/05/2020 14:17	S20-6561	Clubhouse, Casan Residencia Subdivision	7.42 / 30.6	0.10	ABSENCE	ABSENCE	36
10/05/2020 12:05	S20-6510	Water Pump, Block 3 Lot 1, Phase 1A Annex, San Lorenzo Subd.	7.60 / 29.0	0.29	ABSENCE	ABSENCE	< 1
10/05/2020 12:00	S20-6511	Block 5 Lot 25, Phase 1A Annex, San Lorenzo Subd.	7.70 / 29.2	0.32	ABSENCE	ABSENCE	< 1
10/05/2020 11:43	S20-6514	Water Pump, Main Road, Phase 2, Terra Fortuna	7.78 / 29.2	0.53	ABSENCE	ABSENCE	< 1
10/05/2020 11:48	S20-6515	Block 11 Lot 16, Terra Fortuna	7.91 / 28.9	0.61	ABSENCE	ABSENCE	< 1
10/05/2020 12:19	S20-6512	Water Pump, 9999 W, Villa Las Casas	7.43 / 29.1	0.38	ABSENCE	ABSENCE	< 1
10/05/2020 12:27	S20-6513	Block 1 Lot 17, Villa Las Casas	7.24 / 29.6	0.42	ABSENCE	ABSENCE	< 1
10/05/2020 13:30	S20-6562	Drinking Fountain, Malitlit Elementary School	7.44 / 30.5	0.15	ABSENCE	ABSENCE	42

NOT VALID WITHOUT QR CODE



REVIEWED BY:

JETHRO D. ESCOBIN  
Microbiology Unit Manager

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT  
Laboratory Services Manager  
License No(s): (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis.

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna  
CONTACT NO.: (049) 543-1916  
WEBSITE: [www.lagunawater.com.ph](http://www.lagunawater.com.ph)

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature <sup>A</sup> (- / °C)	RESIDUAL CHLORINE <sup>B</sup> (mg/L)	COLIFORM <sup>C</sup>		HPC <sup>D</sup> (CFU/mL)
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20	TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
<b>BRGY. POOC</b>							
10/01/2020 14:54	S20-6481	Water Pump, Villa Mercedes	7.48 / 29.4	0.03	ABSENCE	ABSENCE	< 1
10/01/2020 14:16	S20-6482	Block 2 Lot 1, Villa Mercedes	7.58 / 30.6	0.05	ABSENCE	ABSENCE	< 1
<b>BRGY. PULONG STA. CRUZ</b>							
10/05/2020 14:22	S20-6507	Block 6 Lot 8, Buklod Diwa	7.70 / 29.7	0.02	ABSENCE	ABSENCE	< 1
10/05/2020 11:00	S20-6516	Drinking Fountain 1, Pulong Sta. Cruz Elementary School	7.69 / 29.7	0.02	ABSENCE	ABSENCE	280
10/05/2020 11:12	S20-6517	Drinking Fountain 2, Pulong Sta. Cruz Elementary School	7.58 / 29.4	0.03	ABSENCE	ABSENCE	240
<b>BRGY. SANTO DOMINGO</b>							
10/08/2020 13:44	S20-6751	Clubhouse Santa Rosa Estates II	7.70 / 27.4	0.66	ABSENCE	ABSENCE	< 1

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: HPC – Heterotrophic Plate Count; CFU – Colony Forming Units; MDL – Method Detection Limit; LOQ – Limit of Quantification; NA – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.


METHODS: A – Electrometric; B – Colorimetric; C – Enzyme Substrate; D – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23<sup>rd</sup> Edition

NOT VALID WITHOUT QR CODE



REVIEWED BY:

  
JETHRO D. ESCOBIN  
Microbiology Unit Manager

CERTIFIED CORRECT BY:

  
ANNA KARLA S. GUTIERREZ, RMT  
Laboratory Services Manager  
License No(s). PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis.